



Overview: Part of spill impact on 4" Cawthorne Channel3 Well41S Flowline right of way at Sand-Sand. Picture was taken during Joint Investigation of 4th November 2013.



Close-up: Spill due to corrosion on 4" Cawthorne Channel3 Well41S Flowline at Sand-Sand. Picture was taken during Joint Investigation of 4th November 2013.