



Overview: Part of spill impact on Diebu Creek Well15T flowline right of way at Peremabiri. Picture was taken during Joint Investigation of 17th January 2013.



Close up: Hacksaw cut on Diebu Creek Well15T flowline at Peremabiri. Picture was taken during Joint Investigation of 17th January 2013.



Close up: Loose clamp nut on Diebu Creek Well15T flowline at Peremabiri. Picture was taken during Joint Investigation of 17th January 2013.