



Overview: Part of spill impact on Imo River Well59T flowline at Igiriukwu. Picture taken during Joint Investigation of 20th July, 2011



Close-up: Spill due to illegal fitting on Imo River Well59T flowline at Igiriukwu. Picture taken during Joint Investigation of 20th July, 2011