



Todo: GND trace of X1 is a problem, causes severe stability problems. Needs better and shorter connection !

Todo :Replace RN1 with CAY16-101J8LF

Todo: Use through-hole USB connector (polarity ?)

FILE NAME: GBLiveCam_B.pdsprj	DATE: 30/07/2021
DESIGN TITLE: GBLiveCam	PAGE: 1 of 1
BY: Sean Gonsalves	REV: B