



www.pixelatedproof.co Toll Free No. 18001035499

Motor - Claim Form

Insured Details

Report ID	89824	Report Generated On	2024-05-05 15:21:29
Insured Name	aman	Policy No.	374854
Registration Number	dl1ct7221		
VIN	354678	Cubic Capacity (in Litres)	37
Car Name and Model	elite i20	Email Address	
Incident Description	test		

Vehicle Damage Report

Pixelated Proof

Side: Front

Car Part: Front-door

Detected Damage: Dent, Scratch, Glass Shatter

Damage Percentage: 33.41%

Car Part: Front-window

Detected Damage: Dent, Glass Shatter

Damage Percentage: 91.48%

Car Part: Mirror

Detected Damage: Dent, Glass Shatter

Damage Percentage: 86.01%

Car Part: Windshield

Detected Damage: Dent, Glass Shatter

Damage Percentage: 81.75%

Car Part: Fender

Detected Damage: Scratch

Damage Percentage: 2.84%

Side: Back

Car Part: Back-wheel

Detected Damage: Tire Flat, Tire Flat

Damage Percentage: 99.11%

Car Part: Front-bumper

Detected Damage: Scratch, Dent

Damage Percentage: 81.72%

Car Part: Fender

Detected Damage: Scratch, Dent

Damage Percentage: 15.69%

Car Part: Front-wheel

Detected Damage: Tire Flat, Tire Flat

Damage Percentage: 98.38%

Side: Left

Car Part: Hood

Detected Damage: Dent

Damage Percentage: 0.31%

Car Part: Front-bumper

Detected Damage: Scratch, Scratch, Scratch

Damage Percentage: 41.41%

Car Part: Front-wheel

Detected Damage: Scratch, Tire Flat, Tire Flat

Damage Percentage: 98.54%

Side: Right

Car Part: Quarter-panel

Detected Damage: Dent, Scratch

Damage Percentage: 32.41%

Car Part: Quarter-panel

Detected Damage: Scratch

Damage Percentage: 0.18%

Comprehensive Car Part Damage Analysis

Car Part: Quarter-panel

Total Damage Percentage: 32.59%

Detected Damage Types: Scratch, Dent

Sides with Damage: Right

Replacement Needed: No

Car Part: Front-wheel

Total Damage Percentage: 196.91%

Detected Damage Types: Tire Flat, Scratch

Sides with Damage: Left, Front, Back

Replacement Needed: Yes

Car Part: Back-window

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides with Damage: Front, Right

Replacement Needed: No

Car Part: Trunk

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides with Damage:

Replacement Needed: No

Car Part: Front-door

Total Damage Percentage: 33.41%

Detected Damage Types: Glass Shatter, Scratch, Dent

Sides with Damage: Front

Replacement Needed: No

Car Part: Rocker-panel

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides with Damage: Left

Replacement Needed: No

Car Part: Grille

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Left
Replacement Needed: No

Car Part: Windshield

Total Damage Percentage: 81.75%
Detected Damage Types: Glass Shatter, Dent
Sides with Damage: Left, Front, Right, Back
Replacement Needed: Yes

Car Part: Front-window

Total Damage Percentage: 91.48%
Detected Damage Types: Glass Shatter, Dent
Sides with Damage: Front, Right
Replacement Needed: Yes

Car Part: Back-door

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Front, Right
Replacement Needed: No

Car Part: Headlight

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Left, Back
Replacement Needed: No

Car Part: Back-wheel

Total Damage Percentage: 99.11%
Detected Damage Types: Tire Flat
Sides with Damage: Front, Right, Back
Replacement Needed: Yes

Car Part: Back-windshield

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage:
Replacement Needed: No

Car Part: Hood

Total Damage Percentage: 0.31%
Detected Damage Types: Dent
Sides with Damage: Left, Back
Replacement Needed: No

Car Part: Fender

Total Damage Percentage: 18.53%
Detected Damage Types: Scratch, Dent
Sides with Damage: Front, Back
Replacement Needed: No

Car Part: Tail-light

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Right
Replacement Needed: No

Car Part: License-plate

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Left
Replacement Needed: No

Car Part: Front-bumper

Total Damage Percentage: 123.13%
Detected Damage Types: Scratch, Dent
Sides with Damage: Left, Back
Replacement Needed: Yes

Car Part: Back-bumper

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage: Right
Replacement Needed: No

Car Part: Mirror

Total Damage Percentage: 86.01%
Detected Damage Types: Glass Shatter, Dent
Sides with Damage: Left, Front
Replacement Needed: Yes

Car Part: Roof

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides with Damage:
Replacement Needed: No