



www.pixelatedproof.co Toll Free No. 18001035499

Motor - Claim Form

Insured Details

Report ID	63463	Report Generated On	2024-05-06 23:19:59
Insured Name		Policy No.	
Registration Number			
VIN		Cubic Capacity (in Litres)	
Car Name and Model			
Incident Description			

Vehicle Damage Report

Side: Front

Car Part: Hood

Detected Damage: Dent

Damage Percentage: 0.31%

Car Part: Front-bumper

Detected Damage: Scratch, Scratch, Scratch

Damage Percentage: 41.41%

Car Part: Front-wheel

Detected Damage: Scratch, Tire Flat, Tire Flat

Damage Percentage: 98.54%

Side: Back

Side: Left

Car Part: Front-door

Detected Damage: Dent, Scratch, Glass Shatter

Damage Percentage: 33.41%

Car Part: Front-window

Detected Damage: Dent, Glass Shatter

Damage Percentage: 91.48%

Car Part: Mirror

Detected Damage: Dent, Glass Shatter

Damage Percentage: 86.01%

Car Part: Windshield

Detected Damage: Dent, Glass Shatter

Damage Percentage: 81.75%

Car Part: Fender

Detected Damage: Scratch

Damage Percentage: 2.84%

Side: Right

Car Part: Quarter-panel

Detected Damage: Dent, Scratch

Damage Percentage: 32.41%

Car Part: Quarter-panel

Detected Damage: Scratch

Damage Percentage: 0.18%

Comprehensive Car Part Damage Analysis

Car Part: Quarter-panel

Total Damage Percentage: 32.59%

Detected Damage Types: Scratch, Dent

Sides containing the car part: Right

Replacement Required: No

Repair Required: Painting, Denting

Car Part: Front-wheel

Total Damage Percentage: 98.54%
Detected Damage Types: Scratch, Tire Flat
Sides containing the car part: Left, Front
Replacement Required: Yes
Repair Required: No repair can be performed

Car Part: Back-window

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Left, Right
Replacement Required: No
Repair Required:

Car Part: Trunk

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Back
Replacement Required: No
Repair Required:

Car Part: Front-door

Total Damage Percentage: 33.41%
Detected Damage Types: Glass Shatter, Scratch, Dent
Sides containing the car part: Left
Replacement Required: No
Repair Required: Replacement, Painting, Denting

Car Part: Rocker-panel

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Front, Back
Replacement Required: No
Repair Required:

Car Part: Grille

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Front
Replacement Required: No
Repair Required:

Car Part: Windshield

Total Damage Percentage: 81.75%
Detected Damage Types: Glass Shatter, Dent
Sides containing the car part: Left, Right, Front, Back
Replacement Required: Yes
Repair Required: No repair can be performed

Car Part: Front-window

Total Damage Percentage: 91.48%
Detected Damage Types: Glass Shatter, Dent
Sides containing the car part: Left, Right
Replacement Required: Yes
Repair Required: No repair can be performed

Car Part: Back-door

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Left, Right
Replacement Required: No
Repair Required:

Car Part: Headlight

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Front
Replacement Required: No
Repair Required:

Car Part: Back-wheel

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part: Left, Right
Replacement Required: No
Repair Required:

Car Part: Back-windshield

Total Damage Percentage: 0.00%
Detected Damage Types:
Sides containing the car part:
Replacement Required: No
Repair Required:

Car Part: Hood

Total Damage Percentage: 0.31%
Detected Damage Types: Dent
Sides containing the car part: Front
Replacement Required: No
Repair Required: Denting

Car Part: Fender

Total Damage Percentage: 2.84%
Detected Damage Types: Scratch
Sides containing the car part: Left
Replacement Required: No
Repair Required: Painting

Car Part: Tail-light

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides containing the car part: Right, Back

Replacement Required: No

Repair Required:

Car Part: License-plate

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides containing the car part: Front, Back

Replacement Required: No

Repair Required:

Car Part: Front-bumper

Total Damage Percentage: 41.41%

Detected Damage Types: Scratch

Sides containing the car part: Front

Replacement Required: No

Repair Required: Painting

Car Part: Back-bumper

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides containing the car part: Right

Replacement Required: No

Repair Required:

Car Part: Mirror

Total Damage Percentage: 86.01%

Detected Damage Types: Glass Shatter, Dent

Sides containing the car part: Left, Front

Replacement Required: Yes

Repair Required: No repair can be performed

Car Part: Roof

Total Damage Percentage: 0.00%

Detected Damage Types:

Sides containing the car part:

Replacement Required: No

Repair Required: