

Search this site

Embedded Files

Skip to main content

Skip to navigation

CabinetSense Wiki

- [Home](#)
- [32mm System](#)
- [Build History](#)
- [Closet Systems](#)
- [CNC](#)
- [Common Attributes](#)
 - [5-Piece Panel](#)
 - [Alignment](#)
 - [Banding](#)
 - [Cope and Stick](#)
 - [Faceframe Overlap](#)
 - [Grain Direction](#)
 - [Handle and Knobs](#)
 - [Insets](#)
 - [Joinery](#)
 - [Machining](#)
 - [Material](#)
 - [Other](#)
 - [Reveals](#)
- [Component Library](#)
- [Components](#)
- [Construction Templates](#)
- [Cutlist Plus Integration](#)
- [Dynamic User Components](#)
- [Elevation and Plan Dimensions](#)
- [Frequently Asked Questions](#)
- [Known Issues](#)
- [Menus](#)
- [Plugins, Programs, and Links](#)
- [Scene and Layer Management](#)
- [Shop and Submittal Drawings](#)
- [Sketchup Tutorials](#)
- [Tips and Tricks](#)
- [Troubleshooting](#)
- [Tutorials](#)
- [Videos](#)

[CabinetSense Wiki](#)

Grain Direction

Grain Direction can be an elusive thing to describe accurately. Some systems use the terms width and height but that can lead to problems in a 3d world where rotating your cabinet can give you a totally different perspective on those terms.

We think a better way is to base it on how you see the grain running while looking face on at the component. The terms that you can choose from are:


- Width (X axis)

- Height (Z axis)
- Depth (Y axis)

Look at the cabinet below. Grain direction for any part within the cabinet, is described based on how you see the grain running. Match the direction with the labels from the diagram.

Here are some examples:

- Stretchers: Width (X axis)
- Ends (for vertical grain applications): Height (Z axis)
- Ends (for horizontal grain applications): Depth (Y axis)
- Bottom: Width (X axis)
- Back: Height (Z axis)



Visual Identification of Grain Direction

Unfortunately, at this time CabinetSense does not accurately display grain direction in your model.

