

## TABLE OF CONDITIONS OBSERVED

<b>DEVELOPMENT NAME:</b> BUILDCON	<b>BUILDING:</b> 59	<b>ADDRESS:</b> 270011 Jaida Corners, Sporerport
BIN: 39	BLOCK No.: 57	LOT No.: 73
INSPECTION DATE:06/16/2022	DOB CONTROL No.: 123	INSPECTING A/E: Jamil Deckow

Location	Photo No	Condition Description	Causes	Recommendation	Unit	QTY
146	1	DETERIORATED CONCRETE	AGE & WEATHERING OR MOISTURE INFILTRATION	REPAIR CONCRETE	1R	1S
142	2	BROKEN WINDOW	AGE & WEATHERING OR MECHANICAL IMPACT	REPLACE BROKEN WINDOW	44	67
144	3	CORRODED FIRE ESCAPE	AGE & WEATHERING OR MOISTURE INFILTRATION	REPAIR CORRODED FIRE ESCAPE	3	5
141	1	DETERIORATED CAST STONE	AGE & WEATHERING OR MOISTURE INFILTRATION	REPAIR OR REPLACE CAST STONE	34	78