





X Construction Sdn Bhd
INCIDENT/ACCIDENT INVESTIGATION REPORT

PART A	
Report NO : 161057	
Investigation Team	
1. AnasSHO (Leader)	
2. Amir	
3. Hilmi	
Terms of Reference	
1. Site Of Incident	REF-20240521-DUOMFI
2. Copy Of HIRARC	REF-20240521-LLIN55
3. Interview Victims or Witness	☑
Category of Incident : Fatal	
When and Where did the Incident Occur?	
The incident occurred on 21-05-2025 at 13:12:00. It occurred at Sarawak.	
Description of the incident :	
A fifth-grade student died after being struck by a goalpost while hanging from it.	
Description of property damage (if any) :	
Goalpost has broken.	
How did the incident occur :	
REF-20240521-RWHKD4	
Kid was hanging on a broken and rusty goalpost which eventually broke and cause the fall.	
Findings of the investigation :	
The goalpost is already rusty and on the end of being broken.	
Reported By :	
	
AnasSHO	

X Construction Sdn Bhd
HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ : X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM 	Hirarc No :
Location: Jayyid	Verified By: AnasSHO 	Approved By: AnasPM 	Page : 1 of 2 Date : 21/05/2024

Hazard Identification			Risk Assessment						Risk Control		
No	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
1	Material management	Obstruct Material	Tripping by obstruct material	+short briefing before work +use proper PPE	2	3	6	M			Supervisor
2	Erection & and installation of false work/ temporary structure	Pinch point	Minor Injury	+toolbox briefing +use trained workers +short briefing before work +use proper PPE	2	2	4	L			Supervisor
3	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	M			Supervisor

Rev No:

Issue Date:2024-04-11

X Construction Sdn Bhd

HAZARD IDENTIFICATION, RISK ASSESSMENT, AND RISK CONTROLS REGISTER

Project/HQ : X Construction Sdn Bhd	Description of Job : Falsework and Scaffolding Temporary Structure	Prepared By : AnasPM	Hirarc No : Page : 2 of 2
Location: Jayyid	Verified By: AnasSHO	Approved By: AnasPM	Date : 21/05/2024

Hazard Identification			Risk Assessment						Risk Control		
No	Job Sequence	Hazard	Risk	Current Control	L	S	Score	Index	Opportunity	New Control (Suggestions)	Responsibility
4	Cont	Falling Material	+physical injury +material damage	+toolbox briefing +use trained workers +housekeeping work +any tools need to be secure	3	3	9	M			Supervisor

Rev No:

Issue Date:2024-04-11