



Technical Service Bulletin

No.LTB00132

11

April 2008

Subject/Concern: Transmission Procedure Change

Models:

Defender (LD)	2.4 Puma Diesel	2.4 Puma Diesel VIN- range: 7A732615 Onwards
---------------	-----------------	--

Markets: All

Section: 308-03

Summary:

This Technical Bulletin has been issued for information only, to inform Authorized Repairers of a change in the workshop procedure to remove/install the transmission assembly applicable to Defender(LD) 07MY onwards models.

Cause: In the new procedure the transmission centre console is no longer removed and the gearshift linkage is now removed from below the vehicle. The handbrake assembly is removed from the transfer case and the catalytic converter is removed without having to remove the mounting bracket and heat shield.

NOTE: Other SROs affected by this procedure will also change.

Action: Should it become necessary to remove the transmission assembly applicable to Defender (LD) 07MY onwards models, refer to the updated procedure on GTR.

NOTE: Old Labour Time - Gearbox - transfer gearbox assembly - remove for access - refit- OLD TIME 4.60 - 37.20.03/99

NOTE: Old Labour Time - Transmission - renew - OLD TIME 5.60 - 37.20.02

Labour Time:

Operation Description	Operation No.	Time
New labour time Gearbox - transfer gearbox assembly – remove for access - refit	37.20.03/99	3.8 hours
New labour time Transmission – renew	37.20.02	4.7 hours