

Models LD - Defender

Title Defender 07 My Onwards Clutch Plate

Last Modified 23-APR-2009 08:38

Category Driveline

Symptom 506000 Clutch Concerns

Issue: Modified Clutch Plate identification.

Cause: Land Rover have received a small number of reports that the damper springs in the modified Clutch Plate (supplied as part of the Clutch assembly kit, part number LR012199) appear to have excessive movement. This is not a fault and a small degree of movement around 0.6 mm is normal and will not produce any audible rattle.

Action: Please view the photograph attached to this EPQR that shows how the modified Clutch Plate can be identified and fit the modified Clutch assembly LR012199 where necessary.