

LD - Defender  
LM - New Range Rover  
Models LA - Discovery 3  
LS - Range Rover Sport  
LF - Freelander 2  
Title Power Steering System Flushing  
Procedure.

Last Modified 23-MAR-2009 09:13

Category Chassis

Symptom 303000 Steering/Handling

Issue:

When completing a repair on components in the Power Assisted Steering system, debris may be found within the power steering fluid system which could lead to system contamination and a deterioration in system performance.

Cause:

Internal debris from a suspected component malfunction may result in the power steering fluid becoming contaminated.

Content Action:

After identifying and changing the steering component which caused the contamination, please follow the power steering system flushing procedure in GTR, section 211-00, General Procedures, Power Steering System Flushing.

The power steering system flushing procedure SRO number is 57.15.31

It is no longer necessary to change the entire power steering system when contamination has been found.