

Models LD - Defender

Title Defender Steering Box Warranty Parts  
return

Last Modified 22-MAY-2009 08:56

Category Chassis

Symptom 303000 Steering/Handling

**Issue:** Change to Steering Box parts  
supply & condition of returned units under  
warranty.

**Cause:** To reduce complexity of  
replacement Steering Box supplied  
conditions. All Defender new (outright) and  
exchange Steering boxes will be supplied  
complete with Drop Arm fitted. From June  
2008 onwards.

**Action:** Please ensure that the Drop Arm is  
not removed from the original Steering  
Box when the part is returned  
via warranty. If the Steering Box is returned  
with the arm removed this may invalidate  
the warranty. If you currently have a new  
(outright) or exchange Steering Box in  
stock that does not have a Drop Arm fitted,  
it will be necessary to order a new Drop Arm  
prior to fitment which can be claimed with  
the warranty submission.

#### **IMPORTANT**

**When being returned via a warranty  
claim.**

**For both a new (outright)  
or exchange unit, ensure that the original  
steering box adjustment is not disturbed,  
or any other fixings on the steering box  
assembly not related to it's  
removal/installation.**

**Also to assist quality  
improvements, please complete the  
attached diagnostic form to indicate the  
position of fluid leaks and include it with  
the steering box being returned.**

**NOTE:- Ensure that the O rings on the  
PAS fluid feed/return hose connections  
are replaced when replacing a steering  
box assembly.**