



Technical Service Bulletin

No.LTB00188
24
November 2008

Subject/Concern: Steering Gear Pipe/Hose New Repair Time

Models:		
----------------	--	--

Defender (LD)	2.4 Puma (07 MY onwards)	2.4 Puma (07 MY onwards) VIN- range: 732615 Onwards
---------------	--------------------------	---

Markets: All

Section: 211-00

Summary:

This bulletin is for information only, to inform authorized repairers that a new service repair operation time has been created for replacing the power steering pipe to steering gear on Defender 07MY onwards. No time had previously been created for Defender 07MY onwards.

NOTE: OLD SRO TIME (still exists for vehicles up to 07MY)

NOTE: 57.15.21 – Pipe/hose – feed – steering gear – renew – 0.3 hrs

NOTE: 57.15.22 – Pipe/hose – return – steering gear – renew – 0.9 hrs

Labour Time:		
---------------------	--	--

Operation Description	Operation No.	Time
Pipe/hose – feed – steering gear – renew.	57.15.21	1.4 hours
Pipe/hose – return – steering gear – renew.	57.15.22	1.3 hours