

Faculty of Veterinary Medicine & Animal Science

1. Laboratories (VET 01)

- **Level of Damage:** Full
- **Description of Damage:** Completely flooded Micro, Farm CAADDR, and Biochemistry Labs.
- **Recovery Action:** Repair (Walls, ceiling, electrical repairs, partitions, glass repair).
- **Approximate Recovery Cost (Rs. mn):** 100

2. Administration Buildings (VET 02)

- **Level of Damage:** Partial
- **Description of Damage:** Main Administration, CAADDR, and Farm Animal buildings affected.
- **Recovery Action:** Repair (Ceiling, partitions, glass doors, and electrical systems).
- **Approximate Recovery Cost (Rs. mn):** 8

3. Cafeterias (VET 03)

- **Level of Damage:** Partial
- **Description of Damage:** Student Canteen, cooking area, and goods.
- **Recovery Action:** Floor, walls, electrical wiring, painting, replacing furniture, and other goods (cooking equipment).
- **Approximate Recovery Cost (Rs. mn):** 5

4. Vet Teaching Hospital & Sales Center (VET 04)

- **Level of Damage:** Partial
- **Description of Damage:** Hospital, Postmortem Room, and Sales Center affected.
- **Recovery Action:** Repair (Walls, doors, electrical systems, and partitions).
- **Approximate Recovery Cost (Rs. mn):** 53

5. Furniture (VET 05)

- **Level of Damage:** Full
- **Description of Damage:** Cupboards, tables, chairs, and glass cupboards.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** 100

6. ICT Equipment (VET 06)

- **Level of Damage:** Full
- **Description of Damage:** 40 Computers, 5 Printers, 2 Smart Boards, 50 UPS units.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 15

7. Laboratory Equipment (VET 07)

- **Level of Damage:** Full
- **Description of Damage:** Centrifuges, autoclaves, and incubators.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 980

8. VET Teaching Hospital (Other Equipment) (VET 08)

- **Level of Damage:** Full
- **Description of Damage:** Hospital equipment, theatre tables, and anesthetic machines.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 520

9. Sanitation Facilities (VET 09)

- **Level of Damage:** Full
- **Description of Damage:** Washrooms of affected buildings.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 7

10. Electricity System (VET 10)

- **Level of Damage:** Full
- **Description of Damage:** Main switches, panel boards, and electrical sockets.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 10

11. Internet Connection / System (VET 11)

- **Level of Damage:** Full
- **Description of Damage:** Routers and switches.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 25

12. AC Machines and Systems (VET 12)

- **Level of Damage:** Full
- **Description of Damage:** 20 AC units.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 6

13. Walls / Retaining Walls (VET 13)

- **Level of Damage:** Full
- **Description of Damage:** Collapsed boundary wall and fence.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 10

14. Other Damages (VET 14)

- **Level of Damage:** Full
- **Description of Damage:** Consumables and Chemicals.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** 150

Faculty of management

1. Lecture Halls (MGT 01)

- **Level of Damage:** Minimal
- **Description of Damage:** One Lecture Hall.
- **Recovery Action:** Repair (Walls, replace doors and windows, painting).
- **Approximate Recovery Cost (Rs. mn):** 1

2. Laboratories (MGT 02)

- **Level of Damage:** Full
- **Description of Damage:** Simulation Lab.
- **Recovery Action:** Replace Simulation Lab computers, furniture, and software.
- **Approximate Recovery Cost (Rs. mn):** 100

3. Administration Buildings (MGT 03)

- **Level of Damage:** Full
- **Description of Damage:** Main Administration Floor.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 5

4. Auditorium (MGT 04)

- **Level of Damage:** Full
- **Description of Damage:** One Auditorium.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 2

5. Cafeterias (MGT 05)

- **Level of Damage:** Partial
- **Description of Damage:** Student Canteen.
- **Recovery Action:** Repair (Floor, walls, electrical wiring, painting), replacing furniture and other goods.
- **Approximate Recovery Cost (Rs. mn):** 1

6. Recreation Areas (MGT 06)

- **Level of Damage:** Full
- **Description of Damage:** Full damage to the area.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 10

7. Furniture (MGT 07)

- **Level of Damage:** Full
- **Description of Damage:** Chairs, Tables, and Cupboards.
- **Recovery Action:** Replace and Repair.
- **Approximate Recovery Cost (Rs. mn):** 100

8. ICT Equipment (MGT 08)

- **Level of Damage:** Full
- **Description of Damage:** 240 Computers, Multimedia Projectors, Smart Boards, Printers, and UPS units.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 122

9. Electricity System (MGT 09)

- **Level of Damage:** Full
- **Description of Damage:** Panel Boards, Switches, and Fans.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 2.5

10. Internet Connection / System (MGT 10)

- **Level of Damage:** Full
- **Description of Damage:** Routers and Switches.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 5

11. AC Machines and Systems (MGT 11)

- **Level of Damage:** Full
- **Description of Damage:** Indoor and Outdoor AC Units.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 2

12. Internal Roads (MGT 12)

- **Level of Damage:** Minimal
- **Description of Damage:** Internal Road.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 1

13. Vehicles (MGT 13)

- **Level of Damage:** Partial
- **Description of Damage:** Car and Bus.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 4

Faculty of Agriculture

Faculty of Agriculture

1. Laboratories (AGR 01)

- **Level of Damage:** Partial
- **Description of Damage:** Animal Science Laboratory.
- **Recovery Action:** Repair (Walls, Ceiling, Partitions, Electrical Plugs, and Panel Boards Repair).
- **Approximate Recovery Cost (Rs. mn):** 100

2. Furniture (AGR 02)

- **Level of Damage:** Full
- **Description of Damage:** Cupboards, Tables, Chairs, and Glass Cupboards.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** 3

3. Laboratory Equipment (AGR 03)

- **Level of Damage:** Full
- **Description of Damage:** Scientific Equipment.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 118

4. Sanitation Facilities (AGR 04)

- **Level of Damage:** Full
- **Description of Damage:** Plumbing and Water Pump Connectivity.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 3

5. Electricity System (AGR 05)

- **Level of Damage:** Full
- **Description of Damage:** Main Switches, Panel Boards, Electrical Sockets, and Generator.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 5

6. Internal Roads (AGR 06)

- **Level of Damage:** Full
- **Description of Damage:** 3 Internal Roads.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 5

7. Vehicles (AGR 07)

- **Level of Damage:** Full
- **Description of Damage:** 1 Land Rover 4-wheel Jeep, 1 4-wheel Tractor, 1 2-wheel Tractor, 1 Volkswagen Van, 1 Volkswagen Cab.
- **Recovery Action:** Repair and Replace damaged parts.
- **Approximate Recovery Cost (Rs. mn):** 45

Faculty of Engineering

1. Administration Buildings (ENG 01)

- **Level of Damage:** Partial
- **Description of Damage:** Roof of one building, which is the iconic administrative building of the Faculty of Engineering, University of Peradeniya.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 10

2. Walls / Retaining Walls (ENG 02)

- **Level of Damage:** Full
- **Description of Damage:** The Nanu-Oya bordering the north end of the Faculty of Engineering has eroded into the Faculty Border. The stormwater at building level has flown down, washing away some parts of the soil.
- **Recovery Action:** Construct.
- **Approximate Recovery Cost (Rs. mn):** 45

Faculty of Allied Health Sciences

1. Walls / Retaining Walls (Main Administrative Building) (AHS 1)

- **Level of Damage:** Partial
- **Description of Damage:** Structural cracks (38 visible across the three-storey structure) and ongoing erosion around the Main Administrative Building, which is built on non-original, unstable soil. The erosion poses a progressive risk to the foundation, leading to potential structural failure and collapse, especially during heavy rainfall.
- **Recovery Action:** Immediately construct a retaining wall on three sides of the Main Administrative Building to eliminate the risk of future structural failure and safeguard operations.
- **Approximate Recovery Cost (Rs. mn):** 20

2. Walls / Retaining Walls (Land Behind the Student Canteen) (AHS 2)

- **Level of Damage:** Partial
- **Description of Damage:** Erosion of the land behind the Student Canteen, presenting a significant landslide risk, particularly during periods of intense rainfall, which could damage the canteen structure.
- **Recovery Action:** Expedite the construction of a retaining wall behind the student canteen to stabilize the slope and prevent landslides from impacting the facility.
- **Approximate Recovery Cost (Rs. mn):** 10

3. Walls / Retaining Walls (Pharmaceutical Laboratory Building Complex) (AHS 3)

- **Level of Damage:** Partial
- **Description of Damage:** The Pharmaceutical Laboratory Complex, Department of Pharmacy, lacks a retaining wall, leaving the structure without adequate lateral support. This poses a risk of soil erosion, ground movement, and potential instability during adverse weather conditions.
- **Recovery Action:** Immediately design and construct a suitable retaining wall to provide essential structural reinforcement and safeguard the building from future damage.
- **Approximate Recovery Cost (Rs. mn):** 10

Faculty of Dental Sciences

1. Any Other Equipment - Underground fuel sump (DSC 01)

- **Level of Damage:** Partial
- **Description of Damage:** Underground fuel sump with over 3,300 liters of diesel was flooded, and the diesel filter was affected.
- **Recovery Action:** 1. Replace filters. 2. Clean and re-fill the fuel sump.
- **Approximate Recovery Cost (Rs. mn):** 1

Faculty of Arts

1. Walls / Retaining Walls (Psychology Department Building) (ART 01)

- **Level of Damage:** Partial
- **Description of Damage:** Partial collapse of retaining wall and sinking of soil bank at the Psychology Department Building.
- **Recovery Action:** Reconstruction of Concrete Retaining wall.
- **Approximate Recovery Cost (Rs. mn):** 15

2. Walls / Retaining Walls (Kannangara Building) (ART 02)

- **Level of Damage:** Minimal
- **Description of Damage:** Partial structural cracks in the building wall of the 7-story Kannangara Building.
- **Recovery Action:** Parapet Retaining Wall and any other protective measures.
- **Approximate Recovery Cost (Rs. mn):** 150

Postgraduate Institute of Humanities and Social Sciences (PGIHS)

1. ICT Equipment (PHS 01)

- **Level of Damage:** Partial
- **Description of Damage:** 2 Sound Baffles.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 0.2

2. Any Other Equipment - UPS (PHS 02)

- **Level of Damage:** Full
- **Description of Damage:** 2 UPS units.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** (Missing)

3. Any Other Damages (PHS 03)

- **Level of Damage:** Full
- **Description of Damage:** A number of essential items were lost due to the floods. These include books, notebooks, and diaries, along with a variety of writing tools such as pens, pencils, and markers. Important folders, files, and document holders were also damaged, together with several office supplies including staplers, paper packs, calculators, and rulers. Electronic equipment suffered significant damage as well, with previously used laptop computers and a desktop being rendered unusable. Additionally, chargers, cables, and related accessories were lost, along with external storage devices such as pen drives and hard drives. Several other small electronic items were also affected and destroyed due to water exposure.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** 1.5

Centre For Distance And Continuing Education (CDCE)

1. Furniture (CDC 01)

- **Level of Damage:** Full
- **Description of Damage:** 5 Computer Tables, 2 Office Tables, 35 Student Desks, 2 Chairs.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 0.51

2. Any Other Equipment (CDC 02)

- **Level of Damage:** Full
- **Description of Damage:** 3 Duplo Machines, 2 Photocopy Machines, 1 Paper Shredder, 1 Paper Collecting Machine, 1 Mobile Sound System, 1 Vacuum Cleaner, 1 Refrigerator, 1 Microwave Oven, 1 Pressure Gun, 1 Generator.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 8.5

3. Electricity System (CDC 03)

- **Level of Damage:** Partial
- **Description of Damage:** Main switches, Panel Boards, Electrical sockets.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 5

4. Internet Connection / System (CDC 04)

- **Level of Damage:** Partial
- **Description of Damage:** Routers, Switches.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 7

5. Other Damages (CDC 05)

- **Level of Damage:** Full
- **Description of Damage:** Stationary items at stores.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** 7

Gymnasium and the swimming pool

1. Gymnasium (Wooden Floor) (GYM 01)

- **Level of Damage:** Partial
- **Description of Damage:** Wooden floor is warped (60x30m).
- **Recovery Action:** Attempt to recover through drying, cutting, and polishing with termiticide treatment; full replacement if recovery fails.
- **Approximate Recovery Cost (Rs. mn):** Termiticide treatment (3), cutting and polishing (3), or Replacement (50)

2. Gymnasium (Weight Training Area) (GYM 02)

- **Level of Damage:** Partial
- **Description of Damage:** Weight training area is partially damaged.
- **Recovery Action:** Servicing and restoration.
- **Approximate Recovery Cost (Rs. mn):** 1.5

3. Gymnasium (Wiring) (GYM 03)

- **Level of Damage:** Partial
- **Description of Damage:** Wiring.
- **Recovery Action:** Re-wiring.
- **Approximate Recovery Cost (Rs. mn):** 0.2

4. Swimming Pool (GYM 04)

- **Level of Damage:** Partial
- **Description of Damage:** Damage to the swimming pool structure, retaining wall, and 4 pool pumps.
- **Recovery Action:** Restoration of retaining wall; repair of pool pumps (servicing, drying, and replacement of electronic components/panel boards). Potential full replacement and new retaining wall erection.
- **Approximate Recovery Cost (Rs. mn):** Servicing and drying/electronic components (1), panel boards (1), Replacement (10), New retaining wall/compaction (15)

5. Playgrounds (GYM 05)

- **Level of Damage:** Partial
- **Description of Damage:** Damaged electrical systems, jogging track, completely damaged jumping mattresses, and compromised drainage system.
- **Recovery Action:** Replace electricals and jumping mattresses; restore jogging track and drainage system.
- **Approximate Recovery Cost (Rs. mn):** Electrical restoration (1), Jogging track inclusive of Gabion wall erection (300), Mattresses (0.2), Drainage system restoration (15)

Hostels

1. Sarasavi medura (800 capacity hall) (HST 01)

- **Level of Damage:** Partial
- **Description of Damage:** Structural stability concerns and damaged furniture.
- **Recovery Action:** Replacement of furniture and erection of a retaining wall to ascertain the stability of the hostel.
- **Approximate Recovery Cost (Rs. mn):** Replacement cost of furniture and accessories (10), Erection of an emergency exit and two bridges (6)

2. Senaka Bibile Hall (500 capacity hall) (HST 02)

- **Level of Damage:** Minimal
- **Description of Damage:** Washing out a section near the cafeteria.
- **Recovery Action:** Retaining wall has to be built.
- **Approximate Recovery Cost (Rs. mn):** Retaining wall (3)

Information Technology Center

1. Any Other Buildings (ICT 01)

- **Level of Damage:** Full
- **Description of Damage:** Lower ground floor flooded (1.8m), with silt, mud, and interior damage.
- **Recovery Action:** Restore and rehabilitate interior spaces.
- **Approximate Recovery Cost (Rs. mn):** 2

2. Furniture (ICT 02)

- **Level of Damage:** Full
- **Description of Damage:** 30 tables and 10 chairs destroyed.
- **Recovery Action:** Replace furniture.
- **Approximate Recovery Cost (Rs. mn):** 2.1

3. ICT Equipment (ICT 03)

- **Level of Damage:** Full
- **Description of Damage:** 4 Servers, 1 VoIP Server, 30 Workstations, UPS units, and network fully damaged.
- **Recovery Action:** Replace all ICT equipment.
- **Approximate Recovery Cost (Rs. mn):** 50.84

4. Any Other Equipment (Generator) (ICT 04)

- **Level of Damage:** Partial
- **Description of Damage:** Generator partially exposed to water, requiring repair.
- **Recovery Action:** Repair / rehabilitate generator.
- **Approximate Recovery Cost (Rs. mn):** 3

5. Sanitation Facilities (ICT 05)

- **Level of Damage:** Partial
- **Description of Damage:** Sanitary lines and fittings flooded and contaminated.
- **Recovery Action:** Replace fixtures and restore sanitation.
- **Approximate Recovery Cost (Rs. mn):** 1

6. Electricity System (ICT 06)

- **Level of Damage:** Partial
- **Description of Damage:** Electrical wiring, sockets damaged; sub-circuits failed.
- **Recovery Action:** Rewire and replace circuits.
- **Approximate Recovery Cost (Rs. mn):** 10

7. Internet Connection / System (ICT 07)

- **Level of Damage:** Full
- **Description of Damage:** Network backbone, cabling, 15 switches, 2 racks, 13 patch panels, and IP system destroyed.
- **Recovery Action:** Replace full network layer.
- **Approximate Recovery Cost (Rs. mn):** 50

8. AC Machines and Systems (ICT 08)

- **Level of Damage:** Full
- **Description of Damage:** Four 48,000 BTU AC units inundated; cooling system failed.
- **Recovery Action:** Replace AC units.
- **Approximate Recovery Cost (Rs. mn):** 2

9. Walls / Retaining Walls (ICT 09)

- **Level of Damage:** Partial
- **Description of Damage:** Moisture seepage and plaster damage on walls.
- **Recovery Action:** Repair damaged walls.
- **Approximate Recovery Cost (Rs. mn):** 1

Works Department

1. Recreation Areas (WDT 01)

- **Level of Damage:** Full
- **Description of Damage:** (Missing)
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 100

2. Other Buildings (WDT 02)

- **Level of Damage:** Partial
- **Description of Damage:** Buildings completely flooded, with damage to the wall, roof, ceiling, retaining walls, structures, boundary fences, electronic items, tools, and office furniture.
- **Recovery Action:** Relocate and newly construct Works Department buildings.
- **Approximate Recovery Cost (Rs. mn):** New construction to relocate (200), Replacing electronic and other tools/equipment (10), Furniture (4)

3. ICT Equipment (WDT 03)

- **Level of Damage:** Full
- **Description of Damage:** 40 Computers, Printers, and Photocopiers.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 10

4. Any Other Equipment (WDT 04)

- **Level of Damage:** Full
- **Description of Damage:** Power Tools and Maintenance equipment.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 10

5. Sanitation Facilities (WDT 05)

- **Level of Damage:** Full
- **Description of Damage:** Sanitary lines and fittings flooded and contaminated.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 0.5

6. Sanitation Facilities (Plumbing) (WDT 06)

- **Level of Damage:** Partial
- **Description of Damage:** Plumbing and general repair.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 0.3

7. Electricity System (WDT 07)

- **Level of Damage:** Full
- **Description of Damage:** Main switches, panel boards, and electrical sockets.
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 0.3

8. Internal Roads (WDT 08)

- **Level of Damage:** Full
- **Description of Damage:** Main entrance road.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 0.2

9. Walls / Retaining Walls (WDT 09)

- **Level of Damage:** Partial
- **Description of Damage:** Retaining wall damage.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 5

10. Vehicles (WDT 10)

- **Level of Damage:** Partial
- **Description of Damage:** 2 Tractors.
- **Recovery Action:** Repair.
- **Approximate Recovery Cost (Rs. mn):** 5

11. Any Other Damages (WDT 11)

- **Level of Damage:** Partial
- **Description of Damage:** Electrical Items (Bulbs, Panel Boards), Hardware (Cement, Paints, Thinner), Water Tanks, Computers, Laptops, and Photocopiers.
- **Recovery Action:** Replace.
- **Approximate Recovery Cost (Rs. mn):** Replace (30), Relocation of stores building (40)

Other Buildings

1. Open air theater (OTH 01)

- **Level of Damage:** Full
- **Description of Damage:** Green room is damaged thus needs to be replaced.
- **Recovery Action:** Replacement of the existing green room.
- **Approximate Recovery Cost (Rs. mn):** 50

2. Pre-school (OTH 02)

- **Level of Damage:** Partial
- **Description of Damage:** Damages to the suspended ceiling, door locks and glass sashes, furniture, walls, toys and stationery, appliances, and electronic items.
- **Recovery Action:** Replacement of appliances and other items, mending the ceiling, and painting of walls.
- **Approximate Recovery Cost (Rs. mn):** Replacement of items (1.2), mending the ceiling and wall painting (2)

3. Staff quarters (2 nos) (OTH 03)

- **Level of Damage:** Partial
- **Description of Damage:** Building completely flooded.
- **Recovery Action:** Repairs to the walls, columns, and floor.
- **Approximate Recovery Cost (Rs. mn):** (Missing)

4. Security and Landscape Division (OTH 04)

- **Level of Damage:** Minimal
- **Description of Damage:** Collapse of retaining wall and sinking of soil bank.
- **Recovery Action:** Relocation.
- **Approximate Recovery Cost (Rs. mn):** 75

UOP Main Electricity System (MES 01)

- **Level of Damage:** Partial
- **Description of Damage:** Funding is needed to replace the following items of the university electricity ring substation due to an electricity outage caused by floods: 1. Supply, install, and commission one input, two output, 11 kV, 1 MVA Ring Main Unit (RMU). 2. Supply, install, and commission an Earth fault and over-current protection system with panel, relay, auxiliary circuits, indicators, and displays covering one 1 MVA port and the two 500 kVA ports of the RMU. 3. Additional 11 kV cabling from RMU to 500 kVA transformers (approximately 10m).
- **Recovery Action:** Repair and Replace.
- **Approximate Recovery Cost (Rs. mn):** 8