

| REV | Description | DATE | BY |
|------|--|-----------|--------------|
| v1.0 | Initial Version | 2021.2.2 | zhihuai.Zhou |
| | 1.Change 32M Crystal 2.Change C32,C33 to 15pF | 2024.3.19 | Linus.Liao |
| | 1.Remove R8 2.Add C11 to resolve the issue of data corruption during Flash read operations. | 2025.6.20 | Linus.Liao |

Seeed Studio

TITLE: Seeed Studio XIAO nRF52840 v1.3









Design:

Check:

Date: 2025-09-08

Vision:

Sheet: 1/1



Seeed Studio

TITLE: Seeed Studio XIAO nRF52840 v1.3





Design:

Check:

Date: 2025-09-08

Vision:

Sheet: 1/1



Seeed Studio

TITLE: Seeed Studio XIAO nRF52840 v1.3

Design:

Check:

Sheet: /

Date: 2025-09-08

Vision:

Sheet: 1/1

Title:

Size: User

Date:

Rev:

KiCad E.D.A. 9.0.0

Id: 1/1