

2009 BMW 335i

WBAPL33539A515223

Odometer: 55 005 km

1 Confirmed Code Code

P1449 Diagnostic Module Tank Leakage (DM-TL) Pump Current Too High
Confirmed
/Pending

3 Pending Code Codes

P1449 Diagnostic Module Tank Leakage (DM-TL) Pump Current Too High
Confirmed
/Pending

P1434 Diagnostic Module Tank Leakage (DM-TL)
Pending

P0301 Cylinder 1 Misfire Detected
Pending

0 Permanent Code Codes

1 Junction BoxModule Code

A6CF AUC-Sensor
ACTIVE

1 Advanced Crash and Safety Management Code

93D0 Supply voltage - Undervoltage
HISTORY

7 Engine Codes

2AAF HISTORY	Fuel Pump, plausibility
2B3A ACTIVE	misfire with shutdown cyl. 6
2B3C INTERMITTENT	misfire with shutdown cyl. 8
29F3 ACTIVE	Fuel pressure sensor, electrical
2A22 HISTORY	tank level, correlation
29CD HISTORY	CDKMD00 - misfire detection cylinder 1 in 1. ignition sequence
29D9 HISTORY	misfirings in case of tank filling level too low

3 Dynamic Stability Control Codes

5DCF HISTORY	- pressure sensor rear right plausibility minimum tolerance fault.
5F13 ACTIVE	- brake pad wear: rear axle wear limit reached.
5ED8 HISTORY	- Reverse gear switch: monitoring reports: switch permanent forward

5 COMBOX Media Codes

A36F HISTORY	BlueCore chip error
A378 HISTORY	TCU Communication with airbag control unit faulty - signal missing (ERROR_COM_AIRBAG_ECU)
D68D HISTORY	Waking device has unsuccessfully tried to wake up network. (Error_WAKEUP_Failed)

D690 MOST: Ring fracture
HISTORY

D691 Long and/or frequent unlocks
HISTORY

1 Top Hifi Amplifier Code

D6D0 Ring diagnosis check done (Error_Ring_Diagnose)
HISTORY

2 Car Access System Codes

A0C1 driver KL50L KS
HISTORY

A0B4 fault enginestart starter
HISTORY

1 Sport Automatic Transmission Code

DE10 Break ring diagnosis has been carried out (Error_Ring_Diagnose)
HISTORY

2 Universal Charging and Hands-free System Codes

DE50 Ringbreak diagnostics has been executed (Error_Ring_Diagnose)
HISTORY

DE51 Long and/or frequently unlocks (Error_Unlock_Long)
HISTORY

1 Roof or Rain Module Code

A670 Misting sensor error
ACTIVE

2 Instrument Cluster Codes

A559 KL30g_f cutoff
HISTORY

A554 Alive telephone
HISTORY

2 Gateway Codes

E190 Ring Diagnosis Check done (Error_Ring_Diagnose)
HISTORY

E18D Wake Up Device tried to wake up network 3-times without success.
HISTORY (Error_WakeUp_Failed)

1 Radio Code

ABEC : Error in connection from Radio to Diversity - Wrong Antenna or Diversity
HISTORY connected

10 Footwell Module Codes

A8C4 Break force display right, E92/E93 or US: 2.Right brake light defective, E84: Tail
ACTIVE light right defect

A8C2 Right reverse light defective
ACTIVE

9CB5 Energy saving mode active
HISTORY

A8C6 Day driving light right defective
HISTORY

A8B3 Right rear indicator defect
HISTORY

A8B6 Left brake light defective, PL3 from 07/14 and SA5A1: daytime running light LED
ACTIVE faulty, PL3 from 07/14 and SA896: daytime running light halogen left faulty

A8AF Right front fog light, E90 M3: Day driving light right defect, PL3 from 07/14 and
ACTIVE (SA5A1 or SA896): break light right faulty

A8A9 High beam light or turning light right defective
ACTIVE

A8A8 High beam light or turning light left defective
ACTIVE

A8AE Left front fog light, E90 M3: Day driving light left defect, PL3 from 07/14 and
ACTIVE (SA5A1 or SA896): break light left faulty

1 Air Conditioning Code

9C6C 12V-output peripherie
HISTORY

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.