

### 3.4.1. Inspect for and Remove Corrosion

Estimated Frequency	Estimated Time	Press Down	Suggested Personnel
Annually	2 hours	No	2 persons
Objective			
Metal corrosion is not common, but may occur in certain factory environmental conditions.			
Personal Protective Equipment (PPEs)		Tools/Materials	
<input type="checkbox"/> Gloves (optional)		<ul style="list-style-type: none"><li>• Scotchbrite pad</li><li>• WD 40</li></ul>	

#### Procedure

Inspect press for signs of rust/corrosion. If needed, clean with Scotchbrite pad and apply WD 40.



Figure 29. Rusty surfaces before and after cleaning