

# BASIC ELECTRICAL ENGINEERING

Course Code: EE100



**Dr. Pragnyashree Ray**

Assistant Professor

Dept. of Electrical Engineering,

C. V. Raman Global University, Bhubaneswar, Odisha

# Module 3: BH curve



# BH Curve OR Hysteresis Loop

**Definition:** Hysteresis refers to the lagging of the magnetization of a ferromagnetic material like iron. In other words when a ferromagnetic material is magnetized in one direction, it will not relax back to zero magnetization even when the imposed magnetizing field is removed hence it has to be driven back to zero, a field in the opposite direction needs to be applied.






Fig- BH Curve or Hysteresis Loop

# BH Curve OR Hysteresis Loop



**SOFT** : these ferromagnetic materials have small area as energy loss over B-H Curve is small



**HARD**: these ferromagnetic materials have slarge area as energy loss over B-H Curve is large. These form good magnets.

The amount of work needed to be done in order to align the dipoles of the material parallel to the applied magnetic field is lost in form of heat

If an alternating magnetic field is applied to the material, its magnetization will trace out a loop called a hysteresis loop or B-H Curve. The study is well supported by the "WEISS DOMAIN" theory.

