

Aruba Instant On 1930 Switch Series Release Notes

Software version 1.0.1.0_113



Part Number: 5200-7110
Published: June 2020
Edition: 1

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgments

Microsoft® and Windows® are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

UNIX® is a registered trademark of The Open Group.

All third-party marks are property of their respective owners.

Description

This release note covers software versions for the 1.0 branch of the software.

Version 1.0.1.0_113 is the initial release of major version 1.0.

Product series supported by this software:

Aruba Instant On 1930 Switch Series

Important information

To avoid damage to your equipment, do not interrupt power to the switch during a software update.

Version history

All released versions are fully supported by Aruba, unless noted in the table.

Version number	Release date	Remarks
1.0.1.0_113	2020-06-01	Initial release of the Aruba Instant On 1930 software. Released, fully supported, and posted to the web.

Products supported

This release applies to the following product models:

Product number	Description
JL680A	Aruba Instant On 1930 8G 2SFP Switch
JL681A	Aruba Instant On 1930 8G Class 4 PoE 2SFP 124W Switch
JL682A	Aruba Instant On 1930 24G 4SFP/SFP+ Switch
JL683A	Aruba Instant On 1930 24G Class 4 PoE 4SFP/SFP+ 195W Switch
JL684A	Aruba Instant On 1930 24G Class 4 PoE 4SFP/SFP+ 370W Switch
JL685A	Aruba Instant On 1930 48G 4SFP/SFP+ Switch
JL686A	Aruba Instant On 1930 48G Class 4 PoE 4SFP/SFP+ 370W Switch

Compatibility/interoperability

The switch web agent supports the following web browsers:

Operating system	Browser
Windows 7	Internet Explorer Edge Chrome version 79 or higher Firefox version 73 or higher
Windows 10	Internet Explorer Edge Chrome version 79 or higher Firefox version 73 or higher
Mac OS X 10.12 to 10.14	Safari version 13 or higher Chrome version 79 or higher Firefox version 73 or higher
Linux OS 2.6, 3.11	Chrome version 79 or higher Firefox version 73 or higher



NOTE: Aruba recommends using the most recent version of each browser as of the date of this release note.

Issues and workarounds

The following are known open issues with this branch of the software.

The Symptom statement describes what a user might experience if this is seen on the network. The Scenario statement provides additional environment details and trigger summaries. When available, the Workaround statement provides a workaround to the issue.

Version 1.0.1.0_113

Type	Bug ID	Description
LED	1010_01	<p>Symptom: The cloud LED on the switch flashes indefinitely.</p> <p>Scenario: Upon initial boot up or following a factory reset, the cloud LED flashes indefinitely until the switch is connected to the network or LAN client.</p> <p>Workaround: Connect the switch to the network or a LAN client (for example, laptop or printer).</p>
LLDP	1010_02	<p>Symptom/Scenario: On rare occasions, the LLDP neighbor feature reports an IPv6 address instead of an IPv4 address for remote devices connected to an SFP or SFP+ port.</p> <p>Workaround: Disconnect and reconnect the device.</p>

Contacting support

Main site	<u>https://www.arubainstanton.com/</u>
Support site	<u>https://support.arubainstanton.com/</u>
Social forums and knowledge base	<u>https://community.arubainstanton.com/</u>
Telephone	<u>https://www.arubainstanton.com/contact-support/</u>
EULA	<u>https://www.arubainstanton.com/eula/</u>
Security	<u>https://www.arubanetworks.com/support-services/security-bulletins/</u> Email: <u>mailto:%20aruba-sirt@hpe.com</u>