
1. GENERAL

1.1. OPERATING AT LARNACA APT

STRAIGHT-IN APPROACHES TO RWY 24 IS NOT AUTHORIZED.

1.2. TAXI PROCEDURES

IF operating rwy 06, all acft except general aviation acft are to hold short at D7.

2. ARRIVAL

2.1. COMMUNICATION FAILURE

Type [controller callsign], [aircraft callsign], 7600 through chat or DMs. Enter holding if possible.

3. DEPARTURE

3.1. START-UP, PUSH-BACK AND TAXI PROCEDURES

All acft must activate anti-collision lights before starting engines.
Caution wingtip.

3.2. COMMUNICATION FAILURE

Type [controller callsign], [aircraft callsign], 7600 through chat or DMs.