

First Notice of Loss

2023-06-06T04:00:00Z

Claim Number: CEN23LA157

Incident Date: 2023-04-11T21:00:00Z

Flight

Operator: nan

Purpose: FERY

Airport of Record: SKIATOOK MUNI

Incident Location:

36.356134, -96.010997, Skiatook, Oklahoma, United States

Aircraft

Make: Acro Sport

Model: II

Category: AIR

Amateur Built: True

Number of Engines: 1

Damage

Cause: The pilot's failure to maintain directional control during landing in a gusting crosswind.

Damage: Substantial

Condition: VMC

Injuries

Highest Injury Level: Minor

Number of Serious Injuries: 0

Number of Minor Injuries: 1



Airplane Insurance Policy

Policy Number 33

Active: From 01/01/2024 to 31/12/2024

Policy Holder: nan

For Purpose: FERY

Airport of Record: SKIATOOK MUNI

Aircraft

Make & Model: Acro Sport II

Category: AIR

Coverage:

Covered aircrafts:

Airplanes

Gliders

Helicopters

Gyrocopters

Excluded:

Anything else

Covered:

Pilot Mistakes or failures

Collision with animals, trees or environment

Mechanical due to engine issues, oil starvation, fuel exhaust

Student or instructor mistakes or failures

Unregistered plane or uncertified pilot

Excluded:

Anything else