

## Revision history

### TEA2+ EE Platform Management Team

Date

2021-11-16

Issue	Date	Sheet	Change description
0.1	2020-02-18	All	First Version taken from P4285_DFS_B-Trucks_Air_Compressor
0.2	2020-06-02	All	Replacing old ECEC names by new E-FRC names
0.3	2020-09-02	All	E-FRC Pinout Added. Complete check done with Azra B. <b>CAN_H:4 CAN_L:5 HVIL_IN:6 HVIL_OUT:7</b> and pins <b>A11 &amp; A12</b> Switched on HPP Air Compressor
0.4	2021-02-05	All	E-FRC Pinout Changed according to F.Leroy CO. Supply EF-05:5 changed to EF-05:14.
0.5	2021-11-16	All	E-FRC pin names updated. No change needed in Saber schematics, already updated.


# Air Compressor, 600V

TEA2+ EE Platform Management Team

Date


2021-11-16

Electrical Motor HPP (PN 23586665)



Signal connector in MUC


Electrical Motor HPP (PN 23586665)



Connector A

Connector B



Connector C



600V connector  
Hirschman HPS40-2  
PN 23839629



DFS Power  
Distribution 600V -  
TVJB2 LCC 7



Vehicle connector pinning