



EZCLICK TECH SERVICES PRIVATE LIMITED

Inspection Report

Proposal Info

Proposal No:	QWERTYU852	breakin case Id:	11
Proposal Start Date:	2024-06-20	Proposal End Date:	2025-06-26

Vehicle Info

Chassis No:	098765432123456	Engine no:	12345678
Model:	CITY	Make:	HONDA
Variant:	1.3 LXI	CC:	65
Chassis No:	098765432123456	Engine no:	12345678
Product:	Two Wheeler	Manufacture year:	2023
Fuel Type:	Petrol	Color:	BLACK


Customer Info

Insured Name:	ASDFGH	Mobile No:	7720861565
Email ID:	Kunal.mahadik@indicosmic.com	Additional Email ID:	
Nominee:	QWERTY	Address:	POIUYTREW



Inspection Date: 19/06/2024

# Inspection Checkpoint Survey




Question	Label	Question	Label
Grill:	scratch	Head Lamp(RT):	scratch
Side Turn Light(LT):	broken	Indicator Light(LT):	broken
Fog Lamp(LT):	Not Working	Front Panel:	Not Working
Bonnet:	safe	Left Apron:	safe
Right Apron:	pressed	Left Front Fender:	pressed
Left Front Door:	good	Left Rear Door:	good
Left Pillar Front(A):	Not available	Left Pillar Center(B):	Not available
Left Pillar Rear(C):	scratch	Left Running Board:	scratch
Left Qtr Panel:	broken	boot:	broken
Rear Bumper:	Not Working	Tail lamp(LT):	Not Working
Right Front Render:	safe	Right Front Door:	safe
Right Rear Door:	pressed	Right pillar Front(A):	pressed
Right Pillar Center(B):	good	Right Pillar Rear(C):	good



Inspection Date: 19/06/2024

Question	Label	Question	Label
Tyres/Rim:	broken	Head Lamp(RT):	broken
Side Turn Light(RT):	Not Working	Indicator Light(RT):	Not Working
Fog Lamp(RT):	safe	Tail lamp(RT):	safe
Rr View Mirror(RT):	pressed	Airbag:	pressed

## Inspection Image Reports




Date / Time: 19/06/2024 3:26:47 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Odometer with Engine on Position




Date / Time: 19/06/2024 3:26:55 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Windscreen Outside to Inside






Date / Time: 19/06/2024 3:26:51 pm  
Latitude / Longitude: 19.116153 / 72.8567875



Windscreen Inside to Outside



Date / Time: 19/06/2024 3:26:59 pm  
Latitude / Longitude: 19.116153 / 72.8567875




Front Image



Date / Time: 19/06/2024 3:27:07 pm  
Latitude / Longitude: 19.116153 / 72.8567875



Left Image



Date / Time: 19/06/2024 3:27:16 pm  
Latitude / Longitude: 19.116153 / 72.8567875



Dicky Open



Inspection Date: 19/06/2024






Date / Time: 19/06/2024 3:27:13 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Rear Image




Date / Time: 19/06/2024 3:27:22 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Right Image




Date / Time: 19/06/2024 3:27:26 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Engraved Chassis




Date / Time: 19/06/2024 3:27:35 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Under Carriage Image






Date / Time: 19/06/2024 3:27:30 pm  
Latitude / Longitude: 19.116153 / 72.8567875




Open Engine Compartment



Date / Time: 19/06/2024 3:27:38 pm  
Latitude / Longitude: 19.116153 / 72.8567875




PUC Copy



Date / Time: 19/06/2024 3:27:42 pm  
Latitude / Longitude: 19.116153 / 72.8567875



Dashboard Copy




Date / Time: 19/06/2024 3:27:49 pm  
Latitude / Longitude: 19.116153 / 72.8567875



Pervious Insurance Copy






Date / Time: 19/06/2024 3:27:45 pm  
Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

RC Copy



Date / Time: 19/06/2024 3:27:54 pm  
Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech


Selfie with car



Date / Time: 19/06/2024 3:27:57 pm  
Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech


Additional Image1



Date / Time: 19/06/2024 3:28:11 pm  
Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Additional Image3




Date / Time: 19/06/2024 3:28:06 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Additional Image2




Date / Time: 19/06/2024 3:28:16 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Front Left Image




Date / Time: 19/06/2024 3:28:20 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Front Right Image



Date / Time: 19/06/2024 3:28:45 pm


Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Rear Right Image







Date / Time: 19/06/2024 3:28:24 pm

Latitude / Longitude: 19.116153 / 72.8567875

EZ Click Tech

Rear Left Image



# Declaration


## Agent Declaration



I/We hereby declare, conform and agree that:-  $\pm$  The Motor vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a Third Party for injury or death caused to any person or damages to any property. I have presented the same vehicle for pre-insurance inspection, which I have proposed for insurance. Identification details noted/photographs taken by the inspecting officials are correct. If later on, at anytime it is found that inspected vehicle and damaged/accidental vehicles are different then neither any claim nor any indemnity in respect of either own damage or third party death or injury or property damage loss nor any benefit shall be available to me/us.. Vehicle has been visually inspected in my/ our presence. No damage or no fact which is material to acceptance of this proposal has been hidden/ undisclosed/ withheld by me/us. Damages of vehicle as noted/photographs taken by the inspecting officials are correct. I/We also agree that damages mentioned as per inspection photographs/video shall be excluded in the event of any claim being lodged during the policy period.

## PROPOSER SIGNATURE AND DECLARATION -

I HEREBY AGREE THAT DAMAGES NOTICES DURING THIS INSPECTION SHALL BE EXCLUDED IN THE EVENT OF ANY CLAIM BEING LADGE

A photograph of a handwritten signature in blue ink on lined paper. The signature is written vertically and appears to be 'Ganesh Kumar'.