



TWINGO

Type

X X X

Sub-section

52

52 **SUNROOF**

- Engine:
- Gearbox:

Basic manual: **M.R. 306 - N.T. 316**

ERRATUM

1 - SUBJECT

In Technical Note 316, on page 52-4, the tightening torque given for the rail and deflector mounting nuts is incorrect.

2 - SOLUTION

After an operation requiring the removal of the rails and the deflector, retighten the mounting nuts to a torque of **2 N.m.**

