



	Type	Sub-section
TWINGO	X06 X	75
CLIO II	XB0 X	75
MEGANE	XA0 X	75
LAGUNA	X56 X	75
SAFRANE	B54 X	75

75

REPLACING A SEAT EQUIPPED WITH A SIDE AIR BAG AFTER TRIGGERING OF THE MODULE

Other sub-section concerned: 88

Engine: XXX  
Gearbox: XXX

IMPORTANT

After the SIDE AIR BAG system has been triggered, it is essential that the complete seat be systematically replaced by following the procedure for ordering the complete seat from the Parts Department.



The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed".

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of RENAULT.