

	Tanning salons	Fitness centres
Visited	19	6
Inspected solariums	93	18
Self-service tanning salons or fitness centres	18	6
Staff operated tanning salons or fitness centres	1	0
UV type 3	4	
UV type 4	35	
UV type unknown or marking missing on the solariums	54	18
Missing or insufficient warning (clause 7.1) or not written in Danish (clause 7.13 EN 60335-1) on the solarium or in the cabin	71	12
Missing or insufficient instructions (clause 7.12) or not written in Danish (clause 7.13 EN 60335-1) on the solarium or in the cabin	46	15
Missing or insufficient protection against access to live parts (clause 8)	0	0
Missing or insufficient protection against access to moving parts (clause 20.2 EN 60335-1)	0	0
Solariums with ragged or sharp edges (clause 22.14 EN 60335-1)	6	0
The lid (canopy) of the solarium closes inadvertently (clause 22.101)	22	6
UV emitters over a person insufficient protected against accidental damage (clause 22.103)	0	0
Goggles missing in the cabin or by the solarium	90	18

The above mentioned data are the results of a limited surveillance project carried out in Denmark, to state the safety level of solariums in tanning salons or fitness centres.

30th January 2009