

SCOUT

OBSERVE & REPORT



Property Visual Documentation Report

Property Address: 123 Main Street Columbus, OH 43228

Client Name: John Doe

Date of Service: 1/5/2026

Time Window (Approx.): 12:15 PM – 1:05 PM

Weather Conditions:

☒ Clear ☐ Overcast ☐ Rain ☐ Snow ☐ Other

**Weather conditions may have affected visibility at the time of documentation.*

Report Reference ID: SC-2026-001

Prepared By:

SCOUT – Visual Documentation Services

Service Type:

Non-Inspection Property Documentation

Report Date: 1/7/2026



SCOPE OF SERVICES

Scout provides time-stamped visual documentation of observable property features only. Services are limited to non-invasive, non-destructive visual documentation of areas that were reasonably accessible at the time of the site visit.

Scout does not perform inspections, evaluations, assessments, analysis, testing, measurements, or professional opinions of any kind.

INCLUSIONS

- Visual documentation of accessible exterior areas
- Visual documentation of accessible interior common areas (if applicable)
- Photographic documentation of visually observable features
- Location-based descriptive notes are limited to factual identification of visually observable conditions only.

EXCLUSIONS

This report does not include:

- Inspections of any kind
- Engineering, architectural, or structural analysis
- Code compliance, regulatory, or safety determinations
- Testing, probing, monitoring, or measurements
- Identification of hidden, concealed, or latent conditions
- Opinions regarding cause, responsibility, severity, or repair methods
- Cost estimates, repair pricing, or scope recommendations

LIMITATIONS

Documentation was limited by accessibility, visibility, weather conditions, lighting, and site conditions present at the time of service.

This report reflects only what was visually observable at the specific date and time of documentation. Conditions may change before or after the service. Scout has no obligation to update this report or notify the client of conditions observed outside the documented service date.

USE OF REPORT

This report is not an inspection and is not intended for design, construction, repair planning, engineering evaluation, or regulatory compliance purposes.

Use of this report is limited to the client identified on Page 1. Reliance by third parties is at their own risk unless expressly authorized in writing by Scout.

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



Documentation Index

Content Area	Description	Section
Property Overview	General site description and coverage	Section 1
Exterior Documentation	Area-based exterior photographs	Section 2
Interior Documentation (if applicable)	Area-based interior photographs	Section 3
Comparison / Historical References	Date-to-date visual comparison	Section 4
Repair Logs	Owner provided resolutions by date	Section 5
Documentation History Log	Log of SCOUT Services provided	Section 6

Documentation Date: Refer to Page 1

Documentation Type: Non-inspection visual documentation



Indicates photographs also referenced in the Comparison / Historical References section for visual cross-reference only.

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



1. Property Overview

Property Name: Sample Commercial Property

Property Use:

☒ Commercial ☐ Retail ☐ Office ☐ Multi-Family ☐ Other: _____

Number of Buildings: 2 Buildings

General Site Description: The property includes one or more buildings and associated site improvements such as parking areas, pedestrian walkways, landscaped areas, and site utilities, as visible at the time of documentation. Site layout and features are shown in the photographic sections of this report.

Areas Included:

Areas Excluded:

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.

2. Exterior Documentation

North Elevation



Image 1 - Main Entry -1/5/2026

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



East Elevation



Image 12 - Side Entry - 1/5/2026

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



South Elevation

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



West Elevation

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



Specialty Areas

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



3. Interior Documentation (If Applicable)

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.

4. Comparison / Historical References

Comparative images are provided for visual reference only and do not represent analysis, assessment of progression, causation, or condition change.

North Elevation – Main Entry



Image 1 - Main Entry -1/5/2026



Image 1 - Main Entry -11/9/2025

A visual difference is present between the referenced documentation dates, including cracking visible in the masonry units at the main entry.

East Elevation – Side Entry



Image 12 - Side Entry -1/5/2026



Image 12 - Side Entry -10/8/2025

No visually apparent differences were observed between the referenced documentation dates.

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



5. Repair Logs

The following information was provided by the property owner or client for reference purposes only. Scout has not verified, evaluated, or confirmed the accuracy, completeness, or effectiveness of the items listed below.

Reference ID	Area / Location	Issue Type	Description (Source Listed)	Resolution Method	Resolution Date
RH-001	North Elevation	Masonry	Cracking observed in brick units along lower wall (Owner)	Repointing performed by contractor	03/18/2024
RH-002	Roof Line (West)	Water Intrusion	Water entry reported during heavy rain (Doc)	Flashing repaired and sealed	06/02/2024
RH-003	Parking Area	Pavement	Surface cracking near drain (Doc)	Asphalt patch installed	08/15/2024

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.



6. Documentation History Log

Entry No.	Report Reference ID	Date of Service	Documentation Type	Notes
1	SC-2025-009	03/04/2025	Exterior Documentation	-
2	SC-2025-021	06/09/2025	Exterior & Common Areas	Annual Documentation of Common Area
3	SC-2025-034	09/07/2025	Exterior Documentation	-
4	SC-2025-055	12/08/2025	Exterior Documentation	

Scout has completed 6 total documentation visits for this property since service initiation.

Property Address: 123 Main Street, Columbus, OH 43228

This report provides visual documentation only. It does not constitute an inspection, assessment, certification, or determination of condition, safety, or compliance. Documentation reflects only what was visually captured at the time of the site visit.