

## BREAKWATER BEACH COMMUNITY LIGHT SUMMARY AS OF 10.6.16

ITEM DESCRIPTION	OBSERVATOIN UPON ARRIVAL	ACTION TAKEN	CURRENT CONDITION OF FIXTURE	NEXT STEPS
FIXTURE #1	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #2	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #3	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #4	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #5	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #6	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #7	NOT WORKING	REPLACED BULB	STILL NOT WORKING	IT APPEARS THE THE LIGHT BULB SOCKET IN THIS FIXTURE WILL NEED REPAIRED OR REPLACED
FIXTURE #8	NOT WORKING	REPLACED BULB	STILL NOT WORKING	IT APPEARS THE THE LIGHT BULB SOCKET IN THIS FIXTURE WILL NEED REPAIRED OR REPLACED
FIXTURE #9	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #10	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #11	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #12	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO THE RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED . WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 12-16. THIS PANEL IS LOCATED ON LOT 21
FIXTURE #13	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO THE RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED . WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 12-16. THIS PANEL IS LOCATED ON LOT 21
FIXTURE #14	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO THE RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED . WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 12-16. THIS PANEL IS LOCATED ON LOT 21
FIXTURE #15	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO THE RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED . WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 12-16. THIS PANEL IS LOCATED ON LOT 21
FIXTURE #16	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO THE RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED . WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 12-16. THIS PANEL IS LOCATED ON LOT 21
FIXTURE #17	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #18	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #19	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #20	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #21	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #22	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #23	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #24	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #25	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #26	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #27	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #28	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #29	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS

FIXTURE #30	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED. WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 30,31 & 32 THIS PANEL IS LOCATED ON LOT 39
FIXTURE #31	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED. WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 30,31 & 32 THIS PANEL IS LOCATED ON LOT 39
FIXTURE #32	NOT WORKING	TESTED THE BREAKER AT THE PANEL	STILL NOT WORKING	AT 20 AMP SIEMENS BREAKER WAS TESTED AT THE PANEL AND FOUND THAT THE BREAKER WOULD NOT STAY ENGAGED AND KEPT FAILING TO RESET POSITION. THE BREAKER AT THIS LOCATION WILL NEED TO BE REPLACED. WE BELIEVE THIS BREAKER IS IMPACTING THE OPERATION OF FIXTURES 30,31 & 32 THIS PANEL IS LOCATED ON LOT 39
FIXTURE #33	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #34	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #35	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #36	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #37	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #38	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #39	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #40	WORKING PROPERLY	NONE	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
FIXTURE #41	NOT WORKING	REPLACED BULB	WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 2/3)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 6/7)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 17/18)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 20/21)	GOOD CONDITION / BAD BREAKER IN PANEL	NONE	GOOD CONDITION / BAD BREAKER IN PANEL	REPLACE BREAKER TO CHECK PROPER OPERATION OF LIGHTS
TRASFORMER/PANEL (LOT 24/25)	GOOD CONDITION / PHOTO EYE WAS NOT OPERATION PROPERLY	REPLACED PHOTO EYE	GOOD CONDITION/WORKING PROPERLY	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 28/29)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 32/33)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 35/36)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS
TRASFORMER/PANEL (LOT 39/40)	GOOD CONDITION / BAD BREAKER IN PANEL	NONE	GOOD CONDITION / BAD BREAKER IN PANEL	REPLACE BREAKER TO CHECK PROPER OPERATION OF LIGHTS
TRASFORMER/PANEL (LOT 43/44)	GOOD CONDITION	NONE	GOOD CONDITION	INSPECT ON A ROUTINE BASIS