



14 NORMANDY STREET, ALTON, HANTS, GU34 1BX

TEL: 01420 88883 / 89990 email: info@airsafe.org.uk



Job Number :		AA7403		Certificate Number :		ONE		Analyst :		A. Porter					
Air Monitoring															
								REASSURANCE							
Requirement :				YES / NO		Comments									
3.1 All areas are dry				YES											
3.2 NPU is off and sealed				/											
3.5 Area or volume of enclosure				/ m ²		/ m ³									
Microscope No :		AM004		Flowmeter No :		AFL3		Graticule Dia :		100					
Site Temp (°C) :		14.7		Site Pressure (Mb) :		1022		NPL Test :		5					
								Exposed Air Filter Diameter (mm)		22.52					
<small>Test Type Key : R = Reassurance, B = Background, P = Personal, L = Leak</small> <small>Disclaimer: The following results were obtained from exposed membrane filters cleared by the acetone/triacetin method and examined under phase contrast microscopy as detailed in the current issue of the HSE document HSG248 Asbestos: The analysts' guide for sampling, analysis and clearance procedures. Opinions and interpretations are outside the scope of accreditation.</small>															
Sample No	Test Type	Pump Location	Pump No	Cowl No	Flow Rate (L/min)		Flow Time (Mins)		Duration	Volume (Litres)	No. of Fibres	No. of Fields	Concentration (F/ml)		
					Start	Final	Start	Finish							
A01	R	Basement room 1	AP14	AH 14	10.0	10.0	0826	0914	48	480	½	200	<0.01		
A02	R	Basement room 1	AP 4	AH 17	10.0	10.0	0826	0914	48	480	1	200	<0.01		
Minimum level of detection is 0.01 Fibres per Millilitre (F/ml)															
Plan of Area :				Remarks and Observations :											
Air Test :		PASS		Time :		0936		Date :		22-04-16		Analyst :		A. Porter	
THE AREA IS NOW SATISFACTORY.															
Comments :															
Signature :						(If failed, strike through remaining stages and get the supervisor to sign the acknowledgement)									

ISSUE NUMBER	4	DATE	JUL 2015
--------------	---	------	----------



14 NORMANDY STREET, ALTON, HANTS, GU34 1BX

TEL: 01420 88883 / 89990 email: info@airsafe.org.uk



Certificate of Air Monitoring							
Job Number :	AA7403	Certificate Number :	ONE	Analyst :	A. Porter	Arrival Time :	0815
Name & Address of Client :				Site Address :			
Birtley House Group				Birtley House			
Birtley House				Birtley Road			
Birtley Road				Bramley			
Bramley							
Postcode :	GU5 0LB	Tel :	-	Postcode :	GU5 0LB		
Name & Address of Licensed Asbestos Contractor :				Name of Site Supervisor :			
N/A				-			
				Company :			
				-			
Postcode :		Tel :					
Description of Works :		Basement room 1 – Reassurance air test following discovery of Asbestos insulation					
Debris on walls. Debris is sealed with paint.							
Thorough Visual Inspection							
Requirement :		YES / NO		Comments			
2.1 Area is free from waste, debris, dust, contaminated clothing, waste bags, etc...		N/A					
2.2 Interior surfaces are free from debris and fine settled dust.							
Inspection :		Time :		Date :		Analyst :	
THE AREA WAS FREE OF VISIBLE ASBESTOS WASTE, DEBRIS AND SURFACE DUST.							
Comments :		N/A					
Signature :		(If failed, strike through remaining stages and get the supervisor to sign the acknowledgement)					

This Certificate may only be reproduced in FULL and with the written authority of the issuing laboratory.

ISSUE NUMBER	4	DATE	JUL 2015
--------------	---	------	----------