



*Figure 1 - Cable drum from EOS19*



*Figure 2 - Location of spooling unit after cable parted*