



*Figure 1 - Damaged Cable End*



*Figure 2 - Damaged Cable Section*



*Figure 3 - Cable drum from EOS19*





*Figure 4 - Location of spooling unit after cable parted*