



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** KY417  
**Equipment Type:** Hook  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Hook

**Manufacturer:** Beaver  
**Working Load Limit:** 2t  
**Grade:** 80  
**Type:** Eye Self Locking

#	Description	Status
<b>Link / Hook</b>		
1	Manufacturers Identification	Pass
2	Grade / Nominal Size	Pass
3	Excessive Wear	Pass
4	Twisted, Bent or Gauged	Pass
5	Heat Damage or Weld Splatter	Pass
6	Missing or Damaged Latches	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** KY417  
**Equipment Type:** Hook  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Hook

**Manufacturer:** Beaver  
**Working Load Limit:** 2t  
**Grade:** 80  
**Type:** Eye Self Locking

#	Description	Status
<b>Link / Hook</b>		
1	Manufacturers Identification	Pass
2	Grade / Nominal Size	Pass
3	Excessive Wear	Pass
4	Twisted, Bent or Gauged	Pass
5	Heat Damage or Weld Splatter	Pass
6	Missing or Damaged Latches	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** KY1116  
**Equipment Type:** Hook  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Hook

**Manufacturer:** Beaver  
**Working Load Limit:** 2t  
**Grade:** 80  
**Type:** Eye Self Locking

#	Description	Status
<b>Link / Hook</b>		
1	Manufacturers Identification	Pass
2	Grade / Nominal Size	Pass
3	Excessive Wear	Pass
4	Twisted, Bent or Gauged	Pass
5	Heat Damage or Weld Splatter	Pass
6	Missing or Damaged Latches	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** KY1116  
**Equipment Type:** Hook  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Hook

**Manufacturer:** Beaver  
**Working Load Limit:** 2t  
**Grade:** 80  
**Type:** Eye Self Locking

#	Description	Status
<b>Link / Hook</b>		
1	Manufacturers Identification	Pass
2	Grade / Nominal Size	Pass
3	Excessive Wear	Pass
4	Twisted, Bent or Gauged	Pass
5	Heat Damage or Weld Splatter	Pass
6	Missing or Damaged Latches	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** BJ42  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S 2t  
Working Load Limit: 2.0t

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** BJ42  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S 2t  
Working Load Limit: 2.0t

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** BJ42  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S 2t  
Working Load Limit: 2.0t

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** BJ42  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S 2t  
Working Load Limit: 2.0t

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:19 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** P4408  
**Equipment Type:** Wire Rope Sling  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Wire Rope Sling

**Diameter:** 13mm  
**Number of Legs:** 1  
**Type:** Steel Core  
**Bottom End Fittings:** Thimbled Eyes  
**Top End Fittings:** Thimbled Eyes  
**Working Load Limit:** 2.05T  
**Length:** 1480mm  
**Manufacturer:** Robertson

#	Description	Status
<b>Wire Rope</b>		
1	Manufacturers Identification	Pass
2	Serial Number / Batch Number	Pass
3	WLL including angles for multi leg slings	Pass
4	Excessive Broken Wires	Pass
5	Excessive Wear or Scraping	Pass
6	Evidence of heat damage, acid or caustic burns	Pass
7	Kinks, permanent set, distortion, abrasion	Pass
8	Corrosion	Pass
<b>End fittings / Eyes</b>		
9	Permanent Set, Deformation of end fittings	Pass
10	Distortion	Pass
11	Excessive Corrosion	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** P4407  
**Equipment Type:** Wire Rope Sling  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Wire Rope Sling

**Diameter:** 13mm  
**Number of Legs:** 1  
**Type:** Steel Core  
**Bottom End Fittings:** Thimbled Eyes  
**Top End Fittings:** Thimbled Eyes  
**Working Load Limit:** 2.05T  
**Length:** 1480mm  
**Manufacturer:** Robertson

#	Description	Status
<b>Wire Rope</b>		
1	Manufacturers Identification	Pass
2	Serial Number / Batch Number	Pass
3	WLL including angles for multi leg slings	Pass
4	Excessive Broken Wires	Pass
5	Excessive Wear or Scraping	Pass
6	Evidence of heat damage, acid or caustic burns	Pass
7	Kinks, permanent set, distortion, abrasion	Pass
8	Corrosion	Pass
<b>End fittings / Eyes</b>		
9	Permanent Set, Deformation of end fittings	Pass
10	Distortion	Pass
11	Excessive Corrosion	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** N7538  
**Equipment Type:** Wire Rope Sling  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Wire Rope Sling

**Diameter:** 10mm  
**Number of Legs:** 1  
**Type:** Steel Core  
**Bottom End Fittings:** Thimbled Eyes  
**Top End Fittings:** Thimbled Eyes  
**Working Load Limit:** 1.22T  
**Length:** 1524mm  
**Manufacturer:** RLR

#	Description	Status
<b>Wire Rope</b>		
1	Manufacturers Identification	Pass
2	Serial Number / Batch Number	Pass
3	WLL including angles for multi leg slings	Pass
4	Excessive Broken Wires	Pass
5	Excessive Wear or Scraping	Pass
6	Evidence of heat damage, acid or caustic burns	Pass
7	Kinks, permanent set, distortion, abrasion	Pass
8	Corrosion	Pass
<b>End fittings / Eyes</b>		
9	Permanent Set, Deformation of end fittings	Pass
10	Distortion	Pass
11	Excessive Corrosion	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** N7539  
**Equipment Type:** Wire Rope Sling  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Wire Rope Sling

**Diameter:** 10mm  
**Number of Legs:** 1  
**Type:** Steel Core  
**Bottom End Fittings:** Thimbled Eyes  
**Top End Fittings:** Thimbled Eyes  
**Working Load Limit:** 1.22T  
**Length:** 1524mm  
**Manufacturer:** RLR

#	Description	Status
<b>Wire Rope</b>		
1	Manufacturers Identification	Pass
2	Serial Number / Batch Number	Pass
3	WLL including angles for multi leg slings	Pass
4	Excessive Broken Wires	Pass
5	Excessive Wear or Scraping	Pass
6	Evidence of heat damage, acid or caustic burns	Pass
7	Kinks, permanent set, distortion, abrasion	Pass
8	Corrosion	Pass
<b>End fittings / Eyes</b>		
9	Permanent Set, Deformation of end fittings	Pass
10	Distortion	Pass
11	Excessive Corrosion	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** SWH-D-1403-01  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

**Manufacturer:** Integricert  
**Working Load Limit:** Proof loaded 3000lbs

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** P4412  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

**Type:** Tec Cable Spooler  
**Manufacturer:** Robertsons  
**Working Load Limit:** P/L 3.6T  
**Length:** 700mm

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** ALK001  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

Type: Box swivel  
Manufacturer: arklatex  
Working Load Limit: 495lbs  
Length: 240mm

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** ALK001  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

Type: Box Swivel  
Manufacturer: Arklatex  
Working Load Limit: 495LBS  
Length: 240mm

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** 1310-597  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

**Type:** Wireline Rope Clamp  
**Manufacturer:** LS  
**Working Load Limit:** 20,000lbs

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** 3586-1-12  
**Equipment Type:** Manufactured Products- Other  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Manufactured Products- Other

**Type:** Wire Line Winch ( sheave tripod )!  
**Manufacturer:** RAYHAM ENGINEER  
**Working Load Limit:** 180kg  
**Length:** 1600mm

#	Description	Status
<b>Manufactured Product Other</b>		
1	Serial Number	
2	Manufacturer	

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.



safety



W: lifting.com.au  
E: inspections@jlr.com.au  
P: 1300 977 577



# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** 2NI  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S  
Working Load Limit: 4 3/4T

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person. The safe care and use of this equipment remains the ultimate responsibility of the owner / operator.

# Visual Inspection Report

Page: 1 of 1

Inspection Result: **Pass**

**Customer:** Huracan Pty Ltd  
**Address:** 151 Warooby Lane  
ROMA, QLD 4455  
**Serial No:** BJ42  
**Equipment Type:** Shackle  
**Asset Status:** In Service

**Divison:** Huracan - Roma  
**Location:**  
**Phone:** 0414 717 907  
**Reference #:**  
**Order #:**  
**Inspected On:** 02/07/2018

## Shackle

Type: Bow Safety Pin Gr S  
Working Load Limit: 2.0t

#	Description	Status
<b>Shackle</b>		
1	Manufacturers Identification / Grade & WLL	Pass
2	Twisted, Bent or Gouged	Pass
3	Wrong Pin or Damaged Pin	Pass
4	Heat Damage	Pass

Conducted by:

Tony McLean

Printed Date: July 11, 2018 11:20 PM

A visual inspection of this equipment was completed by a competent person.  
The safe care and use of this equipment remains the ultimate responsibility  
of the owner / operator.