





# FAULTY SITE REPORT



## Summary of Issues

This report outlines the faults identified across 19 sites. Each site has been inspected, and the issues are detailed below. I have color coded each issue.

|             |  |
|-------------|--|
| ELECTRICITY |  |
| EQUIPMENT   |  |
| VANDALIZED  |  |

| SITE NO                 | SITE NAME   | ELECTRICITY | SOLAR | ISSUE DESCRIPTION  | SITE STATUS |
|-------------------------|---|-------------|-------|--|-------------|
| NDZ SITES               |   |             |       |  |             |
| NDZ012                  | GOBHOGOBHO COMMUNITY HALL   |             | ☑     | Site has no power.<br>Solar not responding   | DOWN        |
| NDZ044                  | XOSHEYAKHE COMMUNITY HALL   |             | ☑     | They need to install a meter box.<br>AR damaged  | DOWN        |
| NDZ044 - AR DAMAGED     |   |             |       |  |             |
| NDZ055                  | MPHITHINI COMMUNITY HALL  |             | ☑     | The site has an electricity problem<br>RMS does not get power.   | DOWN        |
| NDZ027                  | MJILA COMMUNITY HALL  |             | ☑     | No power<br>Solar is not powering up.  | DOWN        |
| NDZ028                  | MKHAZANI CUMMUNITY HALL   |             | ☑     | No power<br>Solar is not powering up.  | DOWN        |
| NDZ067                  | NGUDWINI COMMUNITY HALL   |             |       | System stolen  | DOWN        |
| NDZ022                  | MADWALENI COMMUNITY HALL  |             | ☑     | Bracket fell<br>No electricity,<br>We removed exterior equipment (we took outdoor AP, broken solar panel, and small MK with us | DOWN        |
| NDZ022 - PICTURES       |   |             |       |  |             |
|                         |  |             |       |    |             |
|                         |  |             |       |    |             |
| UBU SITES               |   |             |       |  |             |
| UBU010                  | NKWELETSHEINI HALL  |             | ☑     | Solar cables not fully connect<br>The site has no electricity  | DOWN        |
| UBU016                  | EKHUTHULA   |             | ☑     | Electricity has low power voltage<br>Solar not powering  | DOWN        |
| UBU038                  | THULESHE HALL   |             | ☑     | The bracket is now broken<br>The site is extremely windy all seasons.  | DOWN        |
| UBU038 - BEFORE PICTURE |   |             |       |  |             |

|   |                                  |   |   |  |      |
|---|----------------------------------|---|---|--|------|
|   |                                  |  |   |  |      |
| UBU038 - CURRENT PICTURE  |                                  |   |   |  |      |
|   |                                  |  |   |  |      |
| UBU025  | AMAZABEKO<br>COMMUNITY HALL      |   | ☑ | Solar not powering up<br>They stole electricity Cable  | DOWN |
| UBU033  | SHECHE COMMUNITY<br>HALL         |   | ☑ | Solar not powering up<br>Electricity disconnected by Eskom   | DOWN |
| UBU035  | THUMOSONG CENTRE<br>(HIGH FLATS) |   | ☑ | Eskom disconnected electricity<br>Site under construction<br>Solar not powering  | DOWN |
| UBU021  | MZIKI HALL                       |   |   | Site has been vandalized<br>Equipment stolen   | DOWN |
| UBU021 - CURRENT PICTURES   |                                  |   |   |  |      |
|   |                                  |   |   |   |      |
|  |                                  |   |   |    |      |
| UMZ SITES   |                                  |   |   |  |      |
| UMZ009  | QONDOKUHLE<br>COMMUNITY HALL     |   | ☑ | No electricity<br>Site has signal issues   | DOWN |
| UMZ021  | HLOBANI TOURIST<br>CENTRE        |   | ☑ | Fallen bracket (fixed but solar<br>damaged and removed,<br>They need to load electricity token   | DOWN |
| UMZ022  | SMME FACILITY                    |   | ☑ | Site is under construction.<br>They removed our system, and the<br>bracket and solar panel were not<br>presented when equipment was<br>collected | DOWN |
| UMZ022 - CURRENT PICTURES   |                                  |   |   |  |      |
|  |                                  |   |   |    |      |

|        |   |   |   |   |      |
|--------|---|---|---|---|------|
|        |  |   |   |                               |      |
| UMZ035 | WARD 22 COMMUNITY HALL  | ☑ |   | Site has been attended to<br>They need to load units, Site will work  | DOWN |
| UMZ010 | NGUNJINI COMMUNITY HALL   |   | ☑ | <ul style="list-style-type: none"> <li>•No Eskom on site(no eskom cable)</li> <li>•Solar not working</li> </ul> | DOWN |