

Cleaning Roller Earth Spring
MSPRC4582FCZZ

Shearing off during actuation of cleaning roller
Possible C4-20 voltage errors as well as spring fragment falling into the PTC area.




Front Frame, Inverted



Earth Spring


Cleaning Roller



Cleaning Roller Earth Spring
with 2 loops missing

Cleaning Roller

Front Frame, Inverted, Belt Removed



Front Frame, Inverted, Belt Removed

Cleaning Roller Earth Spring

