

COMPAL CONFIDENTIAL

MODEL NAME :

PCB# :DA40000RY00

Revision :






PCB 0D1 LS-6112P REV0 SIDE BTN/B

FPR +SAS+ BTN Board Schematics

AuthenTec AES2550


REV 1.0 2010-06-02


Title			
COVER PAGE			
Size	Document Number		Rev 0.1
Date:	Wednesday, June 02, 2010	Sheet	1 of 3



DVT change D1 to VMZ6.8N

DVT2 move to FPR board!









### Battery Status Behavior

- All batteries charged 100%
- One or more batteries charging
- Not charging
- Slow Blinking @1 Hz: Low Battery Threshold (see Product Spec for details)
- Fast Blinking @2 Hz : Battery Charging Fault (see Product Spec for details)

### Connect to M/B

DVT change to 14 Pin wire



DVT add this diode!

PVT change to SN100000W00!

Title			
Button			
Size	Document Number	Rev	
Custom	<Doc>	<RevCode>	
Date:	Wednesday, June 02, 2010	Sheet	3 of 3

*Change List ~ 1*

Items	Page	Title	Date	Request Owner	Issue Description and Solution Description	Version
1	P1	D1 change to VMZ6.8N	2008/05/14	Compal	DVT change D1 to VMZ6.8N	X 0.2
2	P2	JP1 change to Wire connector	2008/05/14	Compal	ME change FFC to Wire	X 0.2
3	P2	Add D4 for power button	2008/05/14	Compal	System with Batt on s3 will cause vs power issue!	X 0.2
4	P2	change Button part number to SN100000W00	2008/09/02	Compal	PWR button no feeling	X 0.2
5	P1	remove D1 and R5 to LS4655	2008/09/02	Compal/Ice	For ESD requirment	X 0.2
6	P3	Add D17	2008/11/24	Compal	For Buttom LED	X 0.2
7	P2	Change C11 & C13 from "" to "SE000005T80".	2010/03/22	Compal	ME interfere with HW, HW 0805 capacitor have not enough room to locate.	X 0.2
7	P3				Change "SD028220000" to "SD028220080".	X 0.2

Title

Size

Custom

Document Number

Date

Wednesday, June 02, 2010

Sheet

46

of

46

Rev

Code