

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Two Leg Chain Sling				
Type Of Inspection	6 Months				
		Report ID	54055	Page	1/1

Equipment Information		
Location	Tackle board bay 3	Inspected At
I.S.I. Equipment Number	10233498	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture		
Serial Mark / Number	220.1	
SWL(s) For The Configuration Examined	4.25 tom @ 45 deg	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	1) The load hook safety catches are missing - to replace.
D - Observations:	None

General Comments
Inspection carried out with minor defects

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber

Surveyor



Industrial Safety Inspections Ltd Tel: +44 (0) 1675 481779
22-23 Amber Business Village
Amington
Tamworth
Staffordshire
B77 4RP
Email: info@isisafety.com
Web: www.isisafety.com