

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



| Overview | | Client Address | | | |
|--------------------|-------------------------------|--|-------|------|-----|
| Client Ref | | Matthew Higby and Company Unit 16 Charmborough Farm Rural Business Park Charlton Road, Holcombe Radstock Somerset BA3 5FX | | | |
| Description | Lifting Accessories/Web Sling | | | | |
| Type Of Inspection | | | | | |
| | | Report ID | 41335 | Page | 1/1 |

| Equipment Information | | |
|---------------------------------------|----------------------|---|
| Location | | Inspected At |
| I.S.I. Equipment Number | 0124157239 | Matthew Higby and Company Unit 16 Charmborough Farm Rural Business Park Charlton Road, Holcombe Radstock |
| Date Of Manufacture | | |
| Serial Mark / Number | JL080334/1/089 (1 m) | |
| SWL(s) For The Configuration Examined | | |

| Inspection Report | |
|---|------|
| A - Defects Requiring Immediate Rectification: | None |
| B - Defects Requiring rectification within a specified time period: | None |
| C - Other defects: | None |
| D - Observations: | None |

| General Comments |
|---|
| Travelled to site to carry out inspection |

| Declaration |
|---|
| I confirm that the equipment was, thoroughly examined on the 07/02/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate. |

| | |
|----------------------|------------|
| Report Date | 07/02/2024 |
| Next Inspection Date | 07/08/2024 |
| Last Inspection Date | Not Known |

Aaron Jennings

Surveyor

