

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Two Leg Chain Sling				
Type Of Inspection	6 Months				
		Report ID	54057	Page	1/2

Equipment Information		
Location	Tackle board bay 3	Inspected At
I.S.I. Equipment Number	10233506	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture		
Serial Mark / Number	CTR19142	
SWL(s) For The Configuration Examined	4 ton @ 90 deg	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	1) The load hook safety catches are missing - to replace
D - Observations:	1) The load hook links are showing wear in diameter - keep under observation.

General Comments
Inspection carried out with minor defects

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Two Leg Chain Sling				
Type Of Inspection	6 Months				
		Report ID	54057	Page	2/2

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber	
Surveyor	