

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Matthew Higby and Company Unit 16 Charmborough Farm Rural Business Park Charlton Road, Holcombe Radstock Somerset BA3 5FX			
Description	Lifting Accessories/Web Sling				
Type Of Inspection	6 Monthly				
		Report ID	41366	Page	1/1

Equipment Information		
Location		Inspected At
I.S.I. Equipment Number	0124157237	Matthew Higby and Company Unit 16 Charmborough Farm Rural Business Park Charlton Road, Holcombe Radstock
Date Of Manufacture		
Serial Mark / Number	2008040304018 (4 m)	
SWL(s) For The Configuration Examined	3 tonne	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	None
D - Observations:	None

General Comments
Travelled to site to carry out inspection

Declaration
I confirm that the equipment was, thoroughly examined on the 07/02/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	07/02/2024
Next Inspection Date	07/08/2024
Last Inspection Date	Not Known

Aaron Jennings

Surveyor

