

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Four Leg Chain Sling				
Type Of Inspection	6 Months				
		Report ID	54060	Page	1/2

Equipment Information		
Location	Tackle board bay 3	Inspected At
I.S.I. Equipment Number	124194286	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands
Date Of Manufacture		
Serial Mark / Number	RS6391/3	
SWL(s) For The Configuration Examined	3.1 tonne @ 90 deg	

Inspection Report	
A - Defects Requiring Immediate Rectification:	None
B - Defects Requiring rectification within a specified time period:	None
C - Other defects:	1) Two chain anchorages are twisted - to rectify. 2) The load hook safety catches are missing - to replace.
D - Observations:	None

General Comments
Inspection carried out with defects noted

Declaration
I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)



Overview		Client Address			
Client Ref		Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Four Leg Chain Sling				
Type Of Inspection	6 Months				
		Report ID	54060	Page	2/2

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	Not Known

John Keber	
Surveyor	