

3D Metal Printing Proposal

Intro & Scope

Goals

Requirements

- Must use a wire feed welder
- Welder must have a Control System
 - Must measure weld temperature
 - Must measure weld current
 - Must use both previous parameters to estimate current quality of weld
 - Must use “G code” as inputs
 - And must control when material is being deposited
- Must
- Should allow for welder thermal shutdown
- May show amount of wire left on spool

Block Diagram



