


Problems:

- How do we know when we're done?
- Where do we check wire speed?
- When do we adjust wire speed?
- Checking for G1 or G0
 - G1/G0 will be truth table

- Antime machine stops, WS=0

- How will we know CNC speed?



* Second phase of dev

maybe use while

Send 0V Analog signal