

Service Bulletin List

No.	Subject	Date
MSB-98E37-002	NEW SERVICE PROCEDURE FOR POWER STEERING GEARBOX	1999-08-15
MSB-00E35-001	CHANGE TO ERASING OF ASB DIAGNOSTICS CODES	2000-05-30
MSB-98E00-503	CORRECTION TO DIAGNOSIS CODE READING PROCEDURE FOLLOWED WHEN USING WARNING LAMP	1998-12-15

MSB-97E52-004	CHANGE IN ATTACHMENT POSITION OF SR AIR BAG CAUTION LABELS	1998-02-15
MSB-99E23-001	ADDITION OF DESCRIPTION OF ABS IDLE-UP SOLENOID VALVE ABOLISHMENT	1999-12-15
MSB-98E27-501	CORRECTION TO THICKNESS OF DIFFERENTIAL CASE FRICTION DISC	1998-11-15
MSB-99E55-503	OMISSION OF DISASSEMBLY / REASSEMBLY OF A/C COMPRESSOR ASSEMBLY	1999-12-15
MSB-97E52-001	ADDITION OF SRS AIR BAG MAINTENANCE PROCEDURE	1997-04-30
MSB-98E33-501REV	CORRECTION OF PART NUMBER OF PINION HEIGHT GAUGE SET'S COMPONENT PART (REVISED)	1999-09-30
MSB-98E33-501	CORRECTION OF PART NUMBER OF PINION HEIGHT GAUGE SET'S COMPONENT PART	1998-11-15
MSB-00E00-003	YEAR MODEL CHANGES FOR 2001 L200	2000-05-30
MSB-97E13-502	MPI TROUBLESHOOTING	1997-06-15