

NOTE: There are 2 grounds that are NOT connected to each other.
This was done in an attempt to decrease noise in the analog sensor GND.
The MOTOR_GND is the botom copper pour and GND is the top copper pour.
By only connecting these grounds through the driver boards,
this allows the small noisy currents on MOTOR_GND
a lower impedance path back to the power source.

