



1. Turn on the power switch, LCD display, as shown in Figure



OK




NG





NG

2. Fan check

Switch on the power, this fan works



3. Nozzle and hot bed heating inspection : “Prepare” → “Preheat PLA”



OK

4. Back to the origin inspection : “Prepare” → “Auto Home”

X axis will move towards left ,Y axis will move towards back, Z axis will move down,
each axis will stop moving till their limit switch

