

**Moraine Fire Department
ALARM REPORT**

DATE 03/15/95

RUN # 3

METHOD OF ALARM FROM PUBLIC

- | | |
|--|--|
| 1 <input type="checkbox"/> Telephone direct | 6 <input type="checkbox"/> No alarm recd |
| 2 <input type="checkbox"/> Municipal alarm system | 7 <input type="checkbox"/> Tie-line (911) |
| 3 <input checked="" type="checkbox"/> Private alarm system | 8 <input type="checkbox"/> Voice signal municipal alarm signal |
| 4 <input type="checkbox"/> Radio | 9 <input type="checkbox"/> Not classified above |
| 5 <input type="checkbox"/> Verbal | 0 <input type="checkbox"/> Undetermined or not reported |

TIME RECEIVED 06:56 TIME DISPATCHED 06:57

LOCATION 20 Loess Lane

REPORTED AS fire in boiler room, possible hazardous materials

BOX No. TRANSMITTED 0247

	TIME OUT	IN-SERVICE	IN-QUARTERS
RESCUE 1	<u>06:57</u>	<u>07:00</u>	
ENGINE 1	<u>06:57</u>	<u>06:59</u>	
ENGINE 2			
ENGINE 3			
ENGINE 4			
ENGINE 5			
TOWER LADDER 1	<u>06:58</u>	<u>07:02</u>	
LADDER 2			
HAZMAT 1	<u>07:00</u>	<u>07:04</u>	
HAZMAT 2			
FIRST UNIT AT SCENE	<u>Engine 1</u>	TIME	<u>06:59</u>

INITIAL REPORT fire in boiler room; contained quickly

CLASSIFICATION four alarm (treated as worse than it actually was)

PROBABLE CAUSE boxes and trash too close to exposed, old wiring
Inspector Burnham

Name of Operator

Use Reverse Side For Additional Information

** Chief has requested thorough investigation to rule out arson.