

TECHNICAL SERVICE BULLETIN

Number: TSBUMTS-005(PC Card Adaptor RF Int.)

Description Summary: PC Card Adaptor RF Interference

Author: AC/JB

Documented: January 10th 2007

Note: This Technical Service Bulletin (TSB) is provided for information purposes only. Novatel cannot accept any responsibility for the use of information provided in this document.

RESTRICTED PROPRIETARY INFORMATION

THE INFORMATION DISCLOSED HEREIN IS THE EXCLUSIVE PROPERTY OF NOVATEL WIRELESS, INC. AND IS NOT TO BE DISCLOSED WITHOUT THE WRITTEN CONSENT OF NOVATEL WIRELESS, INC. NO PART OF THIS PUBLICATION MAY BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS INCLUDING ELECTRONIC STORAGE, REPRODUCTION, EXECUTION OR TRANSMISSION WITHOUT THE PRIOR WRITTEN CONSENT OF NOVATEL WIRELESS, INC. THE RECIPIENT OF THIS DOCUMENT, BY ITS RETENTION AND USE, AGREES TO RESPECT THE SECURITY STATUS OF THE INFORMATION CONTAINED HEREIN.

This document is intended for limited circulation.

THE INFORMATION CONTAINED IN THIS DOCUMENT IS SUBJECT TO CHANGE WITHOUT NOTICE AND SHOULD NOT BE CONSTRUED AS A COMMITMENT BY NOVATEL WIRELESS, INC. UNLESS SUCH COMMITMENT IS EXPRESSLY GIVEN IN A COVERING DOCUMENT.

© 2006 NOVATEL WIRELESS, INC. ALL RIGHTS RESERVED.

PRODUCT EFFECTED:

- All ExpressCards deployed with the PC Card Universal Adaptor XCA-2, Part Number JU-X00001-1

OPERATING SYSTEMS INVOLVED: N/A

PROBLEM DESCRIPTION:

When an ExpressCard is used with the PC Card Universal Adaptor XCA-2 displaying Part Number JU-X00001-1 on the label, the PC may completely lock up (freeze), requiring a reboot. This has been occasionally observed on a few laptop models. This is only observed when in GPRS mode.


CAUSE:

The reason for this behavior is a hardware problem located in the PC Card Universal Adaptor XCA-2 Part Number JU-X00001-1

SOLUTION:

The solution is to replace the PC Card Universal Adaptor XCA-2, Part Number JU-X00001-1 with PC Card Universal Adaptor XCA-2 Part Number JU-X00001-2

The Part numbers are visible on the label as shown.



IMPORTANT: Should you experience this problem, please contact your Service Provider or the vendor that you bought the PC Card Universal Adaptor from, and request a replacement.