



DO NOT CUT OR MODIFY CAB-0075 FOR THE INLET PRESSURE SENSOR. FOLD AND PLACE EXCESS WIRE IN RACEWAY.

