

Exchequer Court  
25-51 St.Mary Axe  
and 9 St.Helen's  
Place London EC3

---

**Appraisal and  
Testing of Retained  
Elements**

---

Library of Documents  
CD-ROM Version  
User Guide

**Ove Arup & Partners**  
Consulting Engineers



**Ove Arup & Partners**  
Consulting Engineers  
45668/01/DH/BJO  
12 September 1995

13 Fitzroy Street  
London W1P 6BQ  
Telephone 0171 636 1531  
Direct Dialling  
Telephone 0171 465 3319  
Facsimile 0171 465 3679

Mrs S Lovitt  
Clifford Chance  
200 Aldersgate Street  
London  
EC1 4JJ

**ARUP**

Dear Mrs Lovitt

**EXCHEQUER COURT DOCUMENT LIBRARY**

I have pleasure in issuing to you copy number 1 of the CD-ROM version of the Document Library for the Assessment and Testing of the Retained Elements. A User Guide is also enclosed.

This copy is for you to hold on behalf of Spaxe Properties Ltd (in administrative receivership) as agreed with Buro Four Project Services.

Yours sincerely




**David Hadden**

Enc

cc Mr P Heritage - Buro Four

F:\DH\_0090.LET

Aberdeen Birmingham Bristol Cambridge Cardiff Coventry Dundee Edinburgh Glasgow  
Isle of Man Leeds London Manchester Newcastle Nottingham Sheffield Winchester Wrexham  
Africa Australia Europe Hong Kong Japan Middle East South East Asia United States of America





Exchequer Court 25-51 St.Mary Axe and  
9 St.Helen's Place London EC3

**Appraisal and Testing of Retained Elements**

Library of Documents CD-ROM Version  
User Guide

September 1995

**Ove Arup & Partners** Consulting Engineers  
13 Fitzroy Street London W1P 6BQ  
Telephone 0171 636 1531 Facsimile 0171 465 3679

Job number 45668/01/DH



## **CD-ROM DOCUMENT LIBRARY - USER GUIDE**

### **1.0 Hardware and Software Requirements**

The CD-ROM version of the Document Library can be accessed using an IBM-compatible personal computer equipped with a CD-ROM disk drive.

The data files stored on the CD are in .TIF format. They can be read using a suitable document imaging software package such as Watermark. Clearly the specification for the personal computer used must be not less than that required to run the chosen software.

### **2.0 File Structure**

The .TIF files held on the CD reflect the arrangement of the hard copies of the library. Each volume of the paper library has been split into manageable segments for scanning and storage on disk. For example each of Volumes 2, 3 and 4 is stored as a single .TIF file whereas Volume 7.2 is stored as seven such files. The drawings in Volume 20 are each stored as an individual .TIF file.

### **3.0 File Index**

The index which follows lists each .TIF filename, the library volume to which it belongs and a brief description of its contents. The Detailed Index for the Library is included in this guide for ease of reference. By using these documents together any item held in the Library can be located on the CD and viewed or printed out as required.



Exchequer Court - Library of Documents; CD-ROM Version

Filename	Volume	Description
2f1daffb.tif	Vol 01	LIBRARY MAP
2f1db422.tif	Vol 01	EXECUTIVE SUMMARY
2fe1e7c6.tif	Vol 01	USER MANUAL
2f1db5e0.tif	Vol 02	FINAL REPORT WP
2f1db83e.tif	Vol 02	APPENDIX A SUPPORTING DOCUMENTATION
2fe1ed63.tif	Vol 03	INDEPENDENT STRUCT. ENG. SUMMARY REPORT
2fe1f185.tif	Vol 04	DETAILED INDEX
2f1dcdcb.tif	Vol 05	STRATEGY DOCUMENT
2f1dba98.tif	Vol 06	PHASE 1 REPORT WP CONC BELOW GRND LEVEL
2f1dbc26.tif	Vol 06	APP. A PHASE 1 REPORT TEL CONC BLW GRND LV
2f1dc67b.tif	Vol 06	APPENDIX B SUPPORTING DOCUMENTATION
30183507.tif	Vol 06	APPENDIX C SUPPORTING PHOTOGRAPHS
2f1dd0b3.tif	Vol 7-1	PHASE 2 REPORT VOL WP SITE INVESTIGATION
2f1dd161.tif	Vol 7-1	APPENDIX A PHASE 2 REPORT TEL
2f1dd4b5.tif	Vol 7-1	APPENDIX B SUPPORTING DOCUMENTATION
2f1dd5c9.tif	Vol 7-1	APPENDIX C SUPPORTING DOCUMENTATION
2f1dd64c.tif	Vol 7-1	PHASE 2 REPORT ON HEADING WP
2f1dd70f.tif	Vol 7-1	APPENDIX 1.0A HEADING WORKS DOCS
2f1ddb2a.tif	Vol 7-1	APPENDIX 1.0B REMEDIAL WORKS DOCUMENTS
2f1ddcdb.tif	Vol 7-1	APPENDIX 1.0C BACKFILLING HEADING DOCS
30183bed.tif	Vol 7-1	APPENDIX 1.0D PHOTOGRAPHS
2f1ddffe.tif	Vol 7-1	PHASE 2 REPORT INSPCTN OF PILES 36 & 39
2f1de079.tif	Vol 7-1	APPENDIX 2.0A SUPPORTING DOCUMENTATION
2f1de1e9.tif	Vol 7-1	APPENDIX 2.0B SUPPORTING DOCUMENTATION
2f1de23d.tif	Vol 7-1	APPENDIX 2.0C SUPPORTING DOCUMENTATION
30183d2e.tif	Vol 7-1	APPENDIX D SLAB/BITUTHENE SHEAR TEST
2f1de4ca.tif	Vol 7-2	PHASE 2 REPORT VOL 2 WP GROUNDSHOCK CALC
2f1de55b.tif	Vol 7-2	SET 1.0 GROUNDSHOCK ANALYSIS RO
2f1de65a.tif	Vol 7-2	PART 1 RETAINING WALLS AND CONTIG PILES
2f1deabd.tif	Vol 7-2	PART 2 SUB-STRUCTURE INCLUSIVE
2f1deccd.tif	Vol 7-2	PART 3 SUB-STRUCTURE INCLUSIVE
2f1df1bf.tif	Vol 7-2	SET 2.0/Z SUPPORTING DOCUMENTATION
2f1df378.tif	Vol 7-2	SITE REPORT SET 3.0 GROUNDSHOCK REPORT SCL
2f1df586.tif	Vol 7-3	PHASE 2 REPORT VOL 3 WP AIRSHOCK CALCS
30183fc2.tif	Vol 7-3	SET 4.0 AIRSHOCK ANALYSIS RO
2f1df867.tif	Vol 7-3	PART 1 SUPERSTRUCTURE ANALYSIS
2f1dff7c.tif	Vol 7-3	PART 2 IMPULSE CALCULATIONS
2f1e00ad.tif	Vol 7-3	PART 3 RETAINED FACADE
2f1e01ab.tif	Vol 7-3	SET 6.0 SUPPORTING DOCUMENTS
2f1e0378.tif	Vol 08	PHASE 3 REPORT WP RETAINED FACADE AREA
2f1e0419.tif	Vol 08	APPENDIX A PHASE 3 REPORT TEL
2f1e06a5.tif	Vol 08	APPENDIX B SUPPORTING DOCUMENTATION
30184421.tif	Vol 08	APPENDIX C EFFECTS OF BOMB 2
30184698.tif	Vol 08	APPENDIX D SUPPORTING PHOTOGRAPHS



Exchequer Court - Library of Documents; CD-ROM Version

Filename	Volume	Description
2f1e0d5b.tif	Vol 09	PHASE 4 REPORT WP LEB SLAB AREA GD FLR
2f1e0df1.tif	Vol 09	APPENDIX A PHASE 4 REPORT TEL
2f1e0ee7.tif	Vol 09	APPENDIX B SUPPORTING DOCUMENTATION
2f1e141c.tif	Vol 10	PHASE 5 REPORT WP LEVEL - 1 SLAB
2f1e15cd.tif	Vol 10	APPENDIX A PHASE REPORT TEL LEVEL-1 SLAB
2f1e1632.tif	Vol 10	APPENDIX B SUPPORTING DOCUMENTATION
301847f1.tif	Vol 10	APPENDIX C SUPPORTING PHOTOGRAPHS
2f1e175b.tif	Vol 11	PHASE 6 REPORT WP GARDEN AREA STRUCTURES
2f1e179a.tif	Vol 11	APPENDIX A PHASE 6 REPORT TEL
2f1e18ce.tif	Vol 11	APPENDIX B SUPPORTING DOCUMENTATION
301848b3.tif	Vol 11	APPENDIX C SUPPORT PHOTOGRAPHS
2fe1f48a.tif	Vol 12	WATERMAN PARTNERSHIP SUP REPORT
2fe1f92d.tif	Vol 12	APPENDIX A SUP DOCUMENTATION
2fe20f1d.tif	Vol 13	REVIEW MEETING MINUTES (MEETINGS 1-10)
2fe1e1f3.tif	Vol 13	REVIEW MEETING MINUTES (MEETINGS 11-20)
2fe1e54b.tif	Vol 13	REVIEW MEETING MINUTES (MEETINGS 21-30)
2fe35fb5.tif	Vol 13	REVIEW MEETINGS (MEETINGS 31-44)
2fe3612f.tif	Vol 14-1	SOIL STRUCT INTERACT UNDER GROUNDSHOCK
2fe365e7.tif	Vol 14-2	CAPACITY CHECK ON RETAINED ELEMENTS
2fe36697.tif	Vol 14-2	APPENDIX 1 : DESIGN INFORMATION
2fe36855.tif	Vol 14-2	APPENDIX 2 : RELEVANT DRAWINGS
2fe36e17.tif	Vol 14-2	APPENDIX 3 : CALCULATIONS
2f1e19dd.tif	Vol 15	SCHEDULE OF REMEDIAL WORKS
2f1e1a60.tif	Vol 15	APPENDIX A SUPPORTING DOCUMENTATION
2fe37258.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 1 REPORT
2fe374ef.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 2 REPORT
2fe376b1.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 3 REPORT
2fe4ab72.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 4 REPORT
2fe4aed5.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 5 REPORT
2fe4b16b.tif	Vol 16-1	TAYWOOD ENGINEERING PHASE 6 REPORT
2fe4b276.tif	Vol 16-1	TAYWOOD ENG SLAB/BITUTHENE SHEAR TESTS
2fe4b344.tif	Vol 16-2	ROYAL ORD GROUNDSHOCK ANAL 25/3/93
2fe4b43e.tif	Vol 16-2	ROYAL ORD AIRSHOCK ANAL DEC 93
2fe4b649.tif	Vol 16-2	SOIL CONSULT GROUNDSHOCK REPORT MAR 94
2fe4b7d8.tif	Vol 16-2	SEARCH TRAINING INT LTD PROPOSALS
2fe4b87a.tif	Vol 16-2	SOIL CONSULTANTS LTD PROPOSALS
2fe4b911.tif	Vol 16-2	TAYWOOD ENGINEERING TESTING PROPOSALS
2fe4b97f.tif	Vol 17	ARCHITECTS REPORT
2fe4ba10.tif	Vol 18	CONTRACTORS REPORT
2fe4ba7a.tif	Vol 19	MISCELLANEOUS DOCUMENTS



**Volume 20 Drawings**

Filename	Drg. No.	Title
3017bbb3.tif	L/8244/200	R.C DTLS OF CAPPING BEAMS SHT 1
3017bc49.tif	L/8244/201	R.C DTLS OF CAPPING BEAMS SHT 2
3017bca9.tif	L/8244/202	R.C DTLS OF CAPPING BEAMS SHT 3
3017e05c.tif	L/8244/209	R.C DTLS OF CAPPING BEAMS SHT 4
3017eob2.tif	L/8244/211	R.C DTLS OF EXT WALLS & COL SHT 1
3017e119.tif	L/8244/212	R.C DTLS OF WALLS SHT 1
3017e16c.tif	L/8244/213	R.C DTLS OF WALLS SHT 2
3017e1bf.tif	L/8244/214	R.C DTLS OF WALLS SHT 3
3017e276.tif	L/8244/215	R.C DTLS OF WALLS SHT 4
3017e9d6.tif	L/8244/216	R.C DTLS OF WALLS SHT 5
3017e32a.tif	L/8244/220	R.C DTLS OF CAPPING BEAMS SHT 4
3017ed30.tif	L/8244/225	R.C DTLS OF CAPPING BEAMS SHT 6
3017ecb1.tif	L/8244/226	R.C DTLS OF CAPPING BEAMS SHT 7
3017ec46.tif	L/8244/227	R.C DTLS OF CAPPING BEAMS SHT 8
3017ebd6.tif	L/8244/228	R.C DTLS OF CAPPING BEAMS SHT 9
3017eb2d.tif	L/8244/229	R.C DTLS OF CAPPING BEAMS SHT 10
3017eab5.tif	L/8244/230	R.C DTLS OF CAPPING BEAMS SHT 11
3017ed91.tif	L/8244/241	R.C DTLS OF WALLS SHT 6
3017ee02.tif	L/8244/242	R.C DTLS OF WALLS SHT 7
3017eecc.tif	L/8244/243	R.C DTLS OF WALLS SHT 8
3017ee5c.tif	L/8244/244	R.C DTLS OF WALLS SHT 9
3017e970.tif	L/8244/251	R.C DTLS OF WALLS LEVELS -1 to -2
3017fo5d.tif	L/8244/C23	CONCRETE LAYOUT GRD FLR
3017f8dc.tif	L/8244/PD2	DTLS OF SPLICES PLUNGED COLUMN
3017f873.tif	L/8244/P100	ATRIUM STEELWORK LEVEL 3
3017fa84.tif	L/8244/P101	ATRIUM STEELWORK LEVEL 4
3017faf9.tif	L/8244/P102	ATRIUM STEELWORK LEVEL 5
3017baad.tif	L/8244/P104	ATRIUM STEELWORK LEVEL 6
3017bb30.tif	L/8244/P107	ATRIUM STEELWORK LEVEL 7
3017e6fb.tif	L/8244/P20	GARDEN AREA PLANS & DTLS
3017e751.tif	L/8244/P21	LEVEL 2 GENERAL ARRANGEMENT
3017e7ab.tif	L/8244/P22	LEVEL 1 GENERAL ARRANGEMENT
3017e807.tif	L/8244/P23	STRUCTURAL STEELWORK LAYOUT GRD FLR
3017e860.tif	L/8244/P24	STRUCTURAL STEELWORK LAYOUT 1ST FLR
3017e8c5.tif	L/8244/P25	STRUCTURAL STEELWORK LAYOUT 2ND FLR
3017e915.tif	L/8244/P26	STRUCTURAL STEELWORK LAYOUT 3RD FLR
3017fobf.tif	L/8244/P27	STRUCTURAL STEELWORK LAYOUT 4TH FLR
3017f13a.tif	L/8244/P28	STRUCTURAL STEELWORK LAYOUT 5TH FLR
3017f198.tif	L/8244/P29	STRUCTURAL STEELWORK LAYOUT 6TH FLR
3017f1f4.tif	L/8244/P30	STRUCTURAL STEELWORK LAYOUT 7TH FLR
3017f257.tif	L/8244/P31	SECTIONS 1-1 to 13-13
3017f2c4.tif	L/8244/P35	STRUCTURAL STEELWORK LAYOUT 8TH FLR
3017f338.tif	L/8244/P36	BRACING FOR ATRIUM COLUMNS
3017f441.tif	L/8244/P38	BRACING FOR CORES 1,2 & 5
3017f4ad.tif	L/8244/P39	BRACING FOR CORES 4 & 6
3017f57d.tif	L/8244/P49	G.A OF CORES 1-6 AT LEVEL MINUS ONE
3017f511d.tif	L/8244/P50	G.A OF CORES 1-6 AT TYPICAL FLOORS



Exchequer Court - Library of Documents; CD-ROM Version

**Volume 20 Drawings (continued)**

<b>Filename</b>	<b>Drg. No.</b>	<b>Title</b>
3017f6c2.tif	L/8244/P70	COLUMN SCHEDULE SHT 1 OF 9
3017f5f5.tif	L/8244/P71	COLUMN SCHEDULE SHT 2 OF 9
3017f65a.tif	L/8244/P72	COLUMN SCHEDULE SHT 3 OF 9
3017f729.tif	L/8244/P73	COLUMN SCHEDULE SHT 4 OF 9
3017fa14.tif	L/8244/P74	COLUMN SCHEDULE SHT 5 OF 9
3017f947.tif	L/8244/P75	COLUMN SCHEDULE SHT 6 OF 9
3017f9b2.tif	L/8244/P76	COLUMN SCHEDULE SHT 7 OF 9
3017f80d.tif	L/8244/P77	COLUMN SCHEDULE SHT 8 OF 9
3017ef9b.tif	L/8244/P79	TYPICAL COLUMN BASEPLATES
3017e21b.tif	L/8244/P84	ATRIUM STEELWORK KEY PLAN
3017e640.tif	L/8244/P85	ATRIUM STEELWORK LEVEL -1
3017ea29.tif	L/8244/P86	ATRIUM STEELWORK LEVEL 0
3017ef33.tif	L/8244/P87	ATRIUM STEELWORK LEVEL 1
3017f3d6.tif	L/8244/P88	ATRIUM STEELWORK LEVEL 2
3017effe.tif	L/8244/P97	COLUMN SCHEDULE SHT 9 OF 9
3017e6a1.tif	L/8244/PL04	PILE LAYOUT
3017b92c.tif	L/8244/P78	COLUMN SCHEDULE KEYPLAN
3017e37e.tif	L/8244/D1	DEMOLITION WORKS GRD FLR
3017e3d5.tif	L/8859/D2	DEMOLITION WORKS 1ST FLR
3017f79f.tif	L/8859/D4	DEMOLITION WORKS 3RD FLR
3017e477.tif	L/8859/D5	DEMOLITION WORKS 4TH FLR
3017e4c5.tif	L/8859/D6	DEMOLITION WORKS 5TH FLR
3017e514.tif	L/8859/D7	DEMOLITION WORKS 6TH FLR
3017e572.tif	L/8859/D8	DEMOLITION WORKS 7TH FLR
3017e5c6.tif	L/8859/D9	DEMOLITION COLUMN KEYPLAN



## **DETAILED INDEX ORGANISATION**

The DETAILED INDEX is in two SECTIONS.

### **SECTION 1    Library ITEMS**

ITEMS include:

- reports
- drawings
- photographs
- correspondence
- file notes etc.

ITEMS are grouped by ORIGINATOR, e.g. Waterman Partnership, Taywood Engineering Ltd.

ITEM ADDRESS is given by VOLUME NUMBER and SECTION or APPENDIX NUMBER where appropriate. Some VOLUMES contain layers of Appendices. In these cases only the highest level APPENDIX NUMBER is given.

### **SECTION 2    Library TOPICS**

TOPICS include:

- areas or zones of the building
- individual Retained Elements
- particular technical issues and investigations

TOPIC ADDRESS is given by VOLUME NUMBER only

In addition copies of the CONTENTS pages from Waterman Partnership's Strategy Document, Phase Reports and Final Report are included in this Volume along with the CONTENTS page from Ove Arup & Partners' Capacity Check on Retained Elements.



## Item Index

Item	Volume	Section
<b>AMEC</b>		
AMEC/Griffiths-McGee Backfilling method statement	7.1	App. C
AMEC/Renlon: Waterproofing to retained structure 22.2.93	7.1	App. C
Drawing No.BP/HW/01 plan of shaft for pile inspection	7.1	App. C
Drawing No.BP/HW/02 section of shaft for pile inspection	7.1	App. C
Drawing No.BP/HW/03 cross section of heading St. Mary Axe for pile inspection	7.1	App. C
Drawing No.BP/HW/04 long section of heading St. Mary Axe for pile inspection	7.1	App. C
Drawing No.BP/HW/05 location plan of excavations for pile inspection	7.1	App. C
Method statement for demolition of retaining wall grid 'F'.	6	App. B
<b>Buro Four Project Services</b>		
Meeting note dated 30.3.93: To assess the progress of the assessment and testing of retained elements of the existing structure	7.1	App. C
<b>Fitzroy Robinson Ltd</b>		
Blockwork report	17	
<b>John Doyle Construction Ltd</b>		
Letter dated 16.10.90, to AMEC, confirmation of verbal instruction	7.2	Set 2.0/Z
<b>Ove Arup and Partners</b>		
Capacity Check on Retained Elements	14.2	
Letter dated 17.5.93 Re: Video recording of core hole down pile No. 36	7.1	App. C
Letter dated 11.8.93 Re: Video recording of borehole in pile No. 39	7.1	App. C
Letter dated 28.9.93 Signing off phase one report	6	
Letter dated 20.12.93 Signing off phase five report	10	
Letter dated 20.12.93 Signing off phase four report	9	
Letter dated 5.1.94 Signing off phase six report	11	
Letter dated 2.6.94 Signing off phase three report	8	
Letter dated 20.9.94 Signing off phase two report volume one	7.1	
Letter dated 26.9.94 Signing off phase two report volume two	7.2	
Letter dated 27.9.94 Signing off phase two report volume three	7.3	
Letter dated 14.6.94 Airshock review observations	7.3	Set 6.0
Letter dated 15.9.94 finalisation of Airshock calculations review	7.3	Set 6.0
Soil-Structure Interaction Under Groundshock	14.1	
<b>Royal Ordnance</b>		
Airshock analysis, report FSG/R/066	7.3	Set 4.0
	16.2	
Groundshock analysis, 25.3.93	7.2	Set 1.0
	16.2	
<b>Soil Consultants Ltd.</b>		
Foundation analysis	5	App. C
	16.2	
Groundshock report (Geotechnical analysis report)	7.2	Set 3.0
	16.2	



Item	Volume	Section
<b>Search Training International Ltd.</b>		
Explosive effects analysis	5 16.2	App. C
<b>Taywood Engineering Ltd.</b>		
Phase one report (No.1303/93/6545:May 93) Retained concrete substructure	6 16.1	App. A
Phase two report (No.1303/93/6582:June 93) Assessment and testing of retaining wall, capping beam and piled foundations	7.1 16.1	App. A
Phase three report (No.1303/93/6583:July 93) Superstructure in retained facade area	8 16.1	App. A
Phase four report (No.1303/93/6584:June 94) Ground floor structure in LEB switch room area	9 16.1	App. A
Phase five report (No.1303/93/6585:July 93) Level -1 slab and supporting steelwork at cores	10 16.1	App. A
Phase six report (No.1303/93/6784:July 93) Structure in garden area	11 16.1	App. A
Photograph, 2no. cracks in soffit of planter A at grid X2/Y21	1 16.1	App. A
Photograph, 13mm LLI, AT2-AT3, Level 2	8 16.1	App. A
Photograph, 50mm Core into pile No. 36	7.1 16.1	App. A
Photograph, 76mm core into pile No. 39	7.1 16.1	App. A
Photograph, Area of 'Hydrotech' membrane removed in planter A at grid X2/Y21	11 16.1	App. A
Photograph, Beam FF/X23/B-C: Cracks between decking and concrete , prior to testing	8 9 16.1	App. A App. A
Photograph, Beam FF/X23/B-C: Cracks across end face between decking and concrete, prior to testing	8 9 16.1	App. A App. A
Photograph, Beam FF/X23/B-C: Test rig arrangement (Typical)	8 9 16.1	App. A App. A
Photograph, Beam GF/X45/B-C: Test rig arrangement (Typical)	9 16.1	App. A
Photograph, Bituthene 1200 x DPM	7.1 16.1	App. D
Photograph, Capping beam soffit and old concrete wall	7.1 16.1	App. A
Photograph, Capping beam soffit and old concrete wall to vaults	7.1 16.1	App. A



Item	Volume	Section
<b>Taywood Engineering Ltd (cont.)</b>		
Photograph, CCTV system on pile 36	7.1	App. A
	16.1	
Photograph, Concrete failure on sample GF/X47/G-E	9	App. A
	16.1	
Photograph, Concrete slab cast on Servipak	7.1	App. D
	16.1	
Photograph, Cores extracted from location 2	8	App. A
	16.1	
Photograph, Cracks to column, level -2	8	App. A
	16.1	
Photograph, Cracks to soffit of slab between levels -1 and -2	8	App. A
	16.1	
Photograph, Dislodged brickwork in LEB room	9	App. A
	16.1	
Photograph, East elevation of steel frame to retained facade	8	App. A
	16.1	
Photograph, Exposed shear studs, sample GF/X47/G-E	9	App. A
	16.1	
Photograph, Extensive cracking and possible water ingress	8	App. A
	16.1	
Photograph, Failure similar to all tests - Servipak slipped along DPM	7.1	App. D
	16.1	
Photograph, Floor scabbled	7.1	App. D
	16.1	
Photograph, Gauge frame below level 4	8	App. A
	16.1	
Photograph, General arrangement of tests - test No. 3	7.1	App. D
	16.1	
Photograph, General view of core 5 steel work	10	App. A
	16.1	
Photograph, General view of core 6 steel work	10	App. A
	16.1	
Photograph, General view of garden from the North	11	App. A
	16.1	
Photograph, General view of heading and piles	7.1	App. A
	16.1	
Photograph, General view of South East corner of level -1 slab	10	App. A
	16.1	
Photograph, In situ shear stud test - close up	8	App. A
	9	App. A
	16.1	
Photograph, In situ shear stud test - typical arrangement	8	App. A
	9	App. A
	16.1	
Photograph, Leakage along joint outside water test area 4	10	App. A
	16.1	
Photograph, Level -1 slab under full load	10	App. A
	16.1	
Photograph, Level -1, X8 to X12	8	App. A
	16.1	



Item	Volume	Section
<b>Taywood Engineering Ltd (cont.)</b>		
Photograph, Level -1, X36 to X41, Area B	8	App. A
	16.1	
Photograph, Level -1, X45 to X48	8	App. A
	16.1	
Photograph, Level 2 slab, after load tests	8	App. A
	16.1	
Photograph, Loaded end of beam GF/X45/G-E after failure	9	App. A
	16.1	
Photograph, Load test on Level 4, full load	8	App. A
	16.1	
Photograph, Local buckling of Beam 1, Level 7	8	App. A
	16.1	
Photograph, Missing bolts, Beam 6/14, core 6	10	App. A
	16.1	
Photograph, NE elevation of steel frame behind the retained facade	8	App. A
	16.1	
Photograph, North elevation of beam 2, East end at Level 0	9	App. A
	16.1	
Photograph, North elevation of steel frame to retained facade	8	App. A
	16.1	
Photograph, Part East elevations of walls B, D, J, & L at North end of garden	11	App. A
	16.1	
Photograph, Pile 39 Immediately below slab	7.1	App. A
	16.1	
Photograph, Pile 39/Slab interface	7.1	App. A
	16.1	
Photograph, Pile caps and beam soffit at explosion line	7.1	App. A
	16.1	
Photograph, Pile/Slab junction	7.1	App. A
	16.1	
Photograph, Pile top on explosion line	7.1	App. A
	16.1	
Photograph, Planter A, soffit at South East end	11	App. A
	16.1	
Photograph, Sample FF/X20/B-C after testing	8	App. A
	16.1	
Photograph, Servi-Dek spread over DPM	7.1	App. D
	16.1	
Photograph, Servipak laid on Servi-Dek	7.1	App. D
	16.1	
Photograph, Shear stud test arrangement, sample GF/X47/G-E	9	App. A
	16.1	
Photograph, Slab soffit to North of LEB room door	9	App. A
	16.1	
Photograph, Soffit of composite slab to level 6	8	App. A
	16.1	
Photograph, Soffit of Level 0 slab over LEB switch room showing beams 2, 4 & 10	9	App. A
	16.1	
Photograph, South face, South wall, LEB pulling chamber	8	App. A
	16.1	



Item	Volume	Section
<b>Taywood Engineering Ltd (cont.)</b>		
Photograph, South west elevation of retained structure around the LEB switch room	9	App. A
	16.1	
Photograph, Top of pile S4, recast and undamaged	7.1	App. A
	16.1	
Photograph, Transducer No. 6 below level -1 slab	10	App. A
	16.1	
Photograph, Transducer support frame below level-1 slab	10	App. A
	16.1	
Photograph, Typical failure around shear stud	8	App. A
	9	App. A
	16.1	
Photograph, Typical shear stud failure, sample GF/X47/G-E	9	App. A
	16.1	
Photograph, Underside of water test area 1	10	App. A
	16.1	
Photograph, Underside of water test area 2, looking North	10	App. A
	16.1	
Photograph, UPV test and core location 2	8	App. A
	16.1	
Photograph, UPV test and core location 20. Level -1, Area A, X21 to X22	8	App. A
	16.1	
Photograph, View from under planter A, showing parts of Planter B soffit, Walls L, M, &T, and top of level -1 slab	11	App. A
	16.1	
Photograph, Wall A South elevation	11	App. A
	16.1	
Photograph, Wall B East elevation, North end	11	App. A
	16.1	
Photograph, Wall B East elevation, South end	11	App. A
	16.1	
Photograph, Wall C North elevation	11	App. A
	16.1	
Photograph, Wall G South elevation, wall T West elevation at North end and part of level -1 slab	11	App. A
	16.1	
Photograph, Wall P, West elevation	11	App. A
	16.1	
Photograph, Wall T West elevation at South end, and part of level -1 slab	11	App. A
	16.1	
Photograph, Water test areas 1&2	10	App. A
	16.1	
Photograph, Water test area 4	10	App. A
	16.1	
Photograph, Water test area 5, prior to test	10	App. A
	16.1	
Photograph, Water test area 6	10	App. A
	16.1	



Item	Volume	Section
Proposal for inspection and testing of bomb damaged building at St. Mary Axe, London EC3	5	App. A
Report on slab/bituthene shear tests (No. 1303/93/6655:June 1993)	7.1 16.1	App. D
<b>Waterman Partnership</b>		
Airshock assessment calculations	7.3	Set 5.0
BS 8102:1990, extract from, pages 14 & 18	6	App. B
BS 8110:Part 2:1985, extract from, page 3/1	6	App. B
Calculation sheets No.Set 2.0/Z/3.0 (Weight of concrete filled brick vaults)	7.2	Set 2.0/Z
Calculation sheets No.6.0/1-8 (Assessment of core frames)	7.3	Set 6.0
Calculation sheets No. 8859/LTD/1&2 (retained columns level-1 to level -2, elastic recovery due to demolition of superstructure above level -1)	6	App. B
Drawing No. 8859/A (Loading and restraint locations, level 6)	7.3	Set 6.0
Drawing No. L/8244/PL04 (Pile layout)	14.2 20	App. 2
Drawing No. L/8244/PL32 (Splices to plunged column)	20	
Drawing No. L/8244/P05 (St. Mary Axe retaining wall-South elevation)	6	App. A
Drawing No. L/8244/P06 (St. Mary Axe retaining wall-East elevation)	6	App. A
Drawing No. L/8244/P07 (St. Mary Axe retaining wall-West elevation)	6	App. A
Drawing No. L/8244/P08 (St. Mary Axe retaining wall-North elevation)	6	App. A
Drawing No. L/8244/P09 (St. Mary Axe retaining wall-East elevation 2)	6	App. A
Drawing No. L/8244/P20 (St. Mary Axe Garden Area Plans and Details)	11 20	App. A
Drawing No. L/8244/P21 (General Arrangement Level -2)	14.2 20	App. 2
Drawing No. L/8244/P22 (General Arrangement Level -1)	7.3 14.2 20	App. 2
Drawing No. L/8244/P23 Structural Steel Layout : Ground floor	7.3 20	
Drawing No. L/8244/P24 Structural Steel Layout : First floor	20	
Drawing No. L/8244/P25 Structural Steel Layout : Second floor	20	
Drawing No. L/8244/P26 Structural Steel Layout : Third floor	20	
Drawing No. L/8244/P27 Structural Steel Layout : Fourth floor	20	
Drawing No. L/8244/P28 Structural Steel Layout : Fifth floor	20	



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Drawing No. L/8244/P29 Structural Steel Layout : Sixth floor	20	
Drawing No. L/8244/P30 Structural Steel Layout : Seventh floor	20	
Drawing No. L/8244/P31 Sub Structure Sections	20	
Drawing No. L/8244/P35 Structural Steel Layout : Eighth floor	20	
Drawing No. L/8244/P36 Bracing Details : Atrium	14.2 20	App. 2
Drawing No. L/8244/P38 Bracing Cores 1,2&5	14.2 20	App. 2
Drawing No. L/8244/P39 Bracing Cores 4&6	14.2 20	App. 2
Drawing No. L/8244/P49 General Arrangement Cores : Level -1	14.2 20	App. 2
Drawing No. L/8244/P50 General Arrangement Cores 1-6	20	
Drawing No. L/8244/P70 Column Schedule : Sheet 1	14.2 20	App. 2
Drawing No. L/8244/P71 Column Schedule : Sheet 2	14.2 20	App. 2
Drawing No. L/8244/P72 Column Schedule : Sheet 3	14.2 20	App. 2
Drawing No. L/8244/P73 Column Schedule : Sheet 4	14.2 20	App. 2
Drawing No. L/8244/P74 Column Schedule : Sheet 5	14.2 20	App. 2
Drawing No. L/8244/P75 Column Schedule : Sheet 6	14.2 20	App. 2
Drawing No. L/8244/P76 Column Schedule : Sheet 7	14.2 20	App. 2
Drawing No. L/8244/P77 Column Schedule : Sheet 8	14.2 20	App. 2
Drawing No. L/8244/P78 Column Key Plan	14.2 20	App. 2



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Drawing No. L/8244/P79		
Column Base Plates	20	
Drawing No. L/8244/P84		
Atrium Steelwork Key Plan	20	
Drawing No. L/8244/P85		
Atrium Steelwork Level -1	20	
Drawing No. L/8244/P86		
Atrium Steelwork Level 0	20	
Drawing No. L/8244/P87		
Atrium Steelwork Level 1	20	
Drawing No. L/8244/P88		
Atrium Steelwork Level 2	20	
Drawing No. L/8824/P97		
Column Schedule Sheet 9	14.2	App. 2
	20	
Drawing No. L/8244/P100		
Atrium Steelwork Level 3	20	
Drawing No. L/8244/P101		
Atrium Steelwork Level 4	20	
Drawing No. L/8244/P102		
Atrium Steelwork Level 5	20	
Drawing No. L/8244/P104		
Atrium Steelwork Level 6	20	
Drawing No. L/8244/P107		
Atrium Steelwork Level 7	20	
Drawing No. L/8244/200		
RC Details Capping Beams: Sheet 1	20	
Drawing No. L/8244/201		
RC Details Capping Beams: Sheet 2	20	
Drawing No. L/8244/202		
RC Details Capping Beams: Sheet 3	20	
Drawing No. L/8244/209		
RC Details Capping Beams: Sheet 4	20	
Drawing No. L/8244/211		
RC Details External Walls & Columns Level -1/GRD: Sheet 1	20	
Drawing No. L/8244/212		
RC Details Walls level -2/Ground: Sheet 1	20	
Drawing No. L/8244/213		
RC Details Walls level -2/Ground: Sheet 2	20	
Drawing No. L/8244/214		
RC Details Walls level -2/Ground: Sheet 3	20	
Drawing No. L/8244/215		
RC Details Walls level -2/Ground: Sheet 4	20	
Drawing No. L/8244/216		
RC Details Walls level -2/Ground: Sheet 5	20	
Drawing No. L/8244/220		
RC Details Capping Beams: Sheet 5	20	
Drawing No. L/8244/225		
RC Details Capping Beams: Sheet 6	20	



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Drawing No. L/8244/226 RC Details Capping Beams: Sheet 7	20	
Drawing No. L/8244/227 RC Details Capping Beams: Sheet 8	20	
Drawing No. L/8244/228 RC Details Capping Beams: Sheet 9	20	
Drawing No. L/8244/229 RC Details Capping Beams: Sheet 10	20	
Drawing No. L/8244/230 RC Details Capping Beams: Sheet 11	20	
Drawing No. L/8244/241 RC Details Walls level -2/Ground: Sheet 6	20	
Drawing No. L/8244/242 RC Details Walls level -2/Ground: Sheet 7	20	
Drawing No. L/8244/243 RC Details Walls level -2/Ground: Sheet 8	20	
Drawing No. L/8244/244 RC Details Walls level -2/Ground: Sheet 9	20	
Drawing No. L/8244/251 RC Details Walls level -2/Level -1	20	
Drawing No. L/8244/C23 Ground floor concrete layout	14.2 20	App. 2
Drawing No. L/8859/A1 (Key Plan)	5 6 7.1 8 9 10 11	App. B App. B App. B App. B App. B App. B
Drawing No. L/8859/AT/SK/HRW.1.0 (Retaining wall remedial detail)	7.1	App. C
Drawing No. Sketch 8859/AT/01(A3) level 0 ground floor locations of beam/slab test samples	6 7.1 7.2 9	App. B App. C
Drawing No. Sketch 8859/AT/01-H Section through St. Mary Axe sub-structure grid F	7.1	App. C
Drawing No. Sketch 8859/AT/02(A3) locations of beam/slab test samples	8	App. B
Drawing No. Sketch 8859/AT/03(A3) level +2 location of slab load test	8	App. B
Drawing No. Sketch 8859/AT/04(A3) level +4 location of slab load test	8	App. B
Drawing No. Sketch 8859/AT/05(A3) level -1 plan showing locations of water and load tests	10	App. B
Drawing No. Sketch 8859/AT/06(A3) plan showing location of water and load tests over + room locations	10	App. B



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Drawing No. Sketch 8859/AT/07(A3) ground floor plan level 0 showing location of LEB slab area	9	App. B
Drawing No. Sketch 8859/AT/08(A3) level -1 plan showing location of LEB slab area	9	App. B
Drawing No. Sketch 8859/AT/09(A3) garden area Ground floor plan	11	App. B
Drawing No. Sketch 8859/AT/10(A3) garden area plan level -1	11	App. B
Drawing No. Sketch 8859/AT/11(A3) garden area section A-A	11	App. B
Drawing No. Sketch 8859/AT/12(A3) garden area section B-B	11	App. B
Drawing No. Sketch 8859/AT/13(A3) garden area section C-C	11	App. B
Drawing No. Sketch 8859/AT/14(A3) garden area section D-D	11	App. B
Drawing No. Sketch 8859/AT/15(A3) retained facade fixings, section	7.3 8	App. B
Drawing No. Sketch 8859/AT/16(A3) retained facade fixings, plans	7.3 8	App. B
Drawing No. L/8859/D1 (Ground floor)	20	
Drawing No. L/8859/D2 (First floor)	20	
Drawing No. L/8859/D3 (Second floor)	20	
Drawing No. L/8859/D4 (Third floor)	20	
Drawing No. L/8859/D5 (Fourth floor)	20	
Drawing No. L/8859/D6 (Fifth floor)	20	
Drawing No. L/8859/D7 (Sixth floor)	20	
Drawing No. L/8859/D8 (Seventh floor)	20	
Drawing No. L/8859/D9 (Column Key Plan)	20	
Drawing No. L/8859/H/RFB/1 (Plans sheet 1)	8	App. C
Drawing No. L/8859/H/RFB/2 (Plans sheet 2)	8	App. C
Drawing No. L/8859/H/RFB/3 (Section 1-1)	8	App. C
Drawing No. L/8859/RF1 Schematic elevation-St. Helen's Place	8	App. C
Drawing No. L/8859/SK101 Stone repairs to retained facade : major repair locations	8	App. C
Drawing No. L/8859/SK102 Stone repairs to retained facade : photograph locations	8	App. C
Drawing No. L/8859/SK.A2 location plan of heading for pile inspection	5 6	App. B
	7.1	App. B
Drawing No. L/8859C/C87 (retaining wall grid 'F')	6	App. B
Drawing No. L/8859C/PL04 (design review scheme pile layout)	7.1	App. C
	7.2	
Executive summary	1	
Final Report	2	
Ground shock assessment calculations final set Nov.93	7.2	Set 2.0
Ground shock preliminary calculations packages	7.2	Set 2.0/Z
Key plan L/8859/H/1 (Retained facade Bishopsgate bomb)	8	App. C
Letter dated 11.2.93, including sketches No.8859/AT/SK.2A and 3A	7.1	App. C
Letter dated 29.3.93, to STIL, Re: Size and location of bomb	7.2	Set 2.0/Z
Letter dated 31.3.93, to TEL, including sketches No.8859/AT/SK.5 and 6	7.1	App. C
Letter dated 6.4.93, to AMEC, Re: Cutting concrete column casing	6	App. B
Letter dated 12.5.93, to WS Atkins, Re: Fine cracks in columns	6	App. B



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Letter dated 14.5.93, to WS Atkins, Re: Fine cracks in columns	6	App. B
Letter dated 28.5.93, to OAP, Re: core inspection of pile No.39.	7.1	App. C
Letter dated 9.6.93, to OAP, Re: comments made in letter dated 7.6.93	7.1	App. C
Letter dated 1.7.94 review clarification of Airshock assessment parts 1&2	7.3	Set 6.0
Letter dated 22.7.94 review clarification of Airshock assessment part 3	7.3	Set 6.0
Letter dated 3.8.94 review clarification of Airshock assessment part 1 and calculation sheets	7.3	Set 6.0
Phase one report (concrete below ground level)	6	
Phase two report (Site investigation)	7.1	
Phase two report (Heading)	7.1	App. C
Phase two report (Inspection of main foundation piles No.36&39)	7.1	App. C
Phase three report (retained facade area)	8	
Phase four report (LEB slab ground floor)	9	
Phase five report (level -1 slab)	10	
Phase six report (garden area structures)	11	
Photograph, Capping beam IGAS joint prior to over-coating with Sika	7.1	App. C
Photograph, capping beam/piles N5 and N6 Sika render view South	7.1	App. C
Photograph, capping beam/piles S2 and S3 Sika render	7.1	App. C
Photograph, column head X22/Y13 at under side of level -1 slab	6	App. C
Photograph, column X13/Y16 SE corner, junction with level -2 slab	6	App. C
Photograph, Garden area, Planter 'A', post explosion April 1992	11	App. C
Photograph, Garden area, view West, post explosion April 1992	11	App. C
Photograph, level -1 head of column X22/Y13 from level -2	10	App. C
Photograph, level -1 head of column X33/Y8 from level -2	10	App. C
Photograph, level -1, slab load test LT1	10	App. C
Photograph, level -1, slab load test LT1, crash deck and instrumentation supports	10	App. C
Photograph, level -1 slab water test WT4	10	App. C
Photograph, level -1 slab water test WT5 preparation of bunding	10	App. C
Photograph, Pile heading access shaft	7.1	App. C
Photograph, Pile heading access shaft, bottom of	7.1	App. C
Photograph, retained facade second floor, April '92	8	App. D
Photograph, retained facade shear stud test, level +4, stud 'A'	8	App. D
Photograph, retained facade support steelwork, May '93	8	App. D
Photograph, retaining wall level -2, X22/X23	6	App. C
Photograph, retaining wall level -1, X36/X41, ground slab removed	6	App. C
Photograph, retaining wall level -1, X45/X48, ground slab removed	6	App. C
Photograph, retaining wall level -1, X8/X12, ground slab removed	6	App. C
Photograph, St. Helen's Place facade June '92	8	App. D
Photograph, St. Helen's Place facade May '93	8	App. D
Photograph, St. Helen's Place facade, North side junction	8	App. D
Photograph, St. Helen's Place facade, South side junction	8	App. D
Photograph, St. Helen's Place west end, rear of Bishops gate building	8	App. D
Photograph, Top of contiguous piles N3 and N4	7.1	App. C
Photograph, Top of contiguous piles S7 at underside capping beam showing polystyrene at joint with old concrete	7.1	App. C
Photograph, Top of contiguous pile/capping beam, explosion line	7.1	App. C
Photograph, View North along heading towards access shaft	7.1	App. C



Item	Volume	Section
<b>Waterman Partnership (cont.)</b>		
Photograph, View South along heading from access shaft	7.1	App. C
Project record sheet dated 24.2.93: coring through pile No. 36 and rewaterproofing of the capping beam in the heading	7.1	
Project record sheet dated 25.2.93: inspection of heading during application of Gunite	7.1	App. C
Project record sheet dated 26.2.93: inspection of waterproofing repairs, level-1 and level -2 slabs	7.1	App. C
Project record sheet dated 1.3.93: inspection of waterproofing in heading and Boroscope test to pile No. 36	7.1	App. C
Project record sheet dated 2.3.93: inspection of waterproofing in heading and Boroscope test to pile No. 36	7.1	App. C
Project record sheet dated 3.3.93: heading - waterproofing	7.1	App. C
Project record sheet dated 4.3.93: inspection	7.1	App. C
Project record sheet dated 5.3.93: inspection of heading	7.1	App. C
Project record sheet dated 12.3.93: load testing of level -1 slab and backfilling of heading	7.1	App. C
Project record sheet dated 15.3.93: backfilling of heading	7.1	App. C
Project record sheet dated 16.3.93: load testing of level -1 slab and backfilling of heading	7.1	App. C
Project record sheet dated 17.3.93: backfilling of heading and facade	7.1	App. C
Project record sheet dated 18.3.93: backfilling of heading and facade	7.1	App. C
Project record sheet dated 19.3.93: backfilling of heading and facade and core to pile No. 36	7.1	App. C
Project record sheet dated 22.3.93: backfilling of heading and facade and core to pile No. 36	7.1	App. C
Project record sheet dated 7.4.93: core in pile No 39	7.1	App. C
Project record sheet, site visit 27.7.93	11	App. B
Report on effects of bomb 2 on retained facade: November 1993	8	App. C
Schedule for proposed remedial works: Extract for piles No.36&39	7.1	
Schedule of remedial works	15	
Schedule of remedial works, extract from, page 3 plus Conbextra HF specification	7.1	
Specification for Conbextra HF	15	App. A
Specification for Fosroc Nitokit epoxy resin crack injection system	15	App. A
Specification for Sikatop 122	15	App. A
Specification for Sikatop-seal 107	15	App. A
Supplementary report	12	



## Topic Index

Principal location(s) of indexed topics listed only.

Topic	Volume
Airshock analysis, Royal Ordnance	7.3, 16.2
Airshock calculations	7.3, 16.2
Basement slab (level -2)	6, 16.1
Bishopsgate explosion 24.4.93	8
BombCAD computer program	5, 7.3, 16.2
Bomb size	7.2, 7.3, 16.2
Boroscope inspection	7.1, 16.1
Brick vaults (in St. Mary Axe)	6, 7.1, 7.2, 16.1
Capacity check on Retained Elements, Ove Arup & Partners	14.2
Concrete encasement to steel columns	6, 8, 16.1
Contiguous piled wall	7.1, 16.1
Cores in concrete	
Piles No. 36 & 39	7.1, 16.1
Retaining walls	6, 16.1
Cracks in concrete elements	
All areas	16.1
Concrete below ground	6
Garden Area	11
LEB Area	9
Level -1 slab	10
Piled foundations	7.1
Slabs at Retained Facade area	8
Demolition works	5
Drawings	20
Retaining wall grid 'F'	6
Drawings	20
DYNA 3-D computer program	14.1
Executive Summary, Waterman Partnership	1



Topic	Volume
Final Report, Waterman Partnership	2
Foundation analysis, Soil Consultants Ltd	5, 16.2
Geotechnical Analysis Report, Soil Consultants Ltd.	7.2, 16.2
Glossary of Terms	1
Groundshock Analysis, Royal Ordnance	7.2, 16.2
Groundshock calculations	7.2, 16.2
Guide to using the Library	1
Hammer tests (to slab soffits)	8, 9, 16.1
Heading	7.1, 16.1
Integrity testing of piles	7.1, 16.1
LEB area	9, 16.1
Level -1 slab	6, 10, 16.1
Level -2 slab (basement slab)	6, 16.1
Library Enquiry Flow Chart	1
Library Enquiry Sample	1
Library map	1
Load tests	
All tests	16.1
Beam/slab shear tests	8, 9
Bituthene shear test	7.1
Level -1 slab	10
Level +2 slab	8
Level +4 slab	8
Shear stud tests	8, 9
Masonry	
LEB area walls	9, 16.1
Level -1 and Level -2	17
Retained Facade	8, 16.1
Non-destructive testing	6, 7.1, 16.1



Topic	Volume
Phase Reports, Taywood Engineering Ltd	
All phases	16.1
Phase 1	6
Phase 2	7.1
Phase 3	8
Phase 4	9
Phase 5	10
Phase 6	11
Phase reports, Waterman Partnership	
Phase 1	6
Phase 2	7.1, 7.2, 7.3
Phase 3	8
Phase 4	9
Phase 5	10
Phase 6	11
PIGLET computer program	7.2, 16.2
Project Directory	5
PUNDIT testing	6, 16.1
Remedial Works Schedule, Waterman Partnership	15
Retained Facade and supporting structure	
Calculations	7.3, 16.2
Inspections and tests	8, 16.1
Retaining wall on St. Mary Axe	
Calculations	7.2, 16.2
Inspections and tests	6, 7.1, 16.1
Review Meeting minutes	13
Shear studs	8, 9, 10, 16.1
Soil Structure Interaction Report, Ove Arup & Partners	14.1
Summary Report, Ove Arup & Partners	3
Supplementary report, Waterman Partnership	12
Temporary stability of Retained Facade	8
Trial pit on St. Mary Axe	6, 16.1
Video record	7.1, 16.1
Volume Descriptions	1



Topic	Volume
WALLAP computer program	7.2, 16.2
Wall piles	7.1, 16.1
Water protection membrane	7.1, 16.1
Water tests (level -1 slab)	10
Weld tests	
LEB slab area	9, 16.1
Level -1 slab	10, 16.1
Retained Facade area	8, 16.1